



## **B.5** DA05 Hamstreet

Area overview			
Area (km²)	2.1		
Drainage assets/systems	Туре	Known Issues/problems	Responsibility
	-76-		y
Sewer Network	Sewer (foul and surface water)	There are issues linked with Southern Water Sewers	Southern Water
Watercourses	Main River	Known fluvial issues associated with the Second Speringbrook Sewer M28	Environment Agency
Watercourses, drains and ditches	Non- Main River	Known fluvial issues associated with the ordinary watercourse at Woodchurch Road and Rolvenden Station.	Kent County Council and Ashford Borough Council
Watercourses, drains and ditches	Non- Main River	Known fluvial issues associated with IDB Drains - Second Speringbrook Sewer M28 and Bournewood	Romney Marsh IDB
Watercourses, drains and ditches	Non- Main River	No specific known problems	Riparian
Flood risk			
Receptor	Source	Pathway	Historic Evidence
neceptor	Source	ratiiway	HISTORIC EVIDENCE
A: Hamstreet (north)	Heavy rainfall resulting in surface water run off and overloaded sewers.  Surface water (blocked drains/ gullies)  Fluvial	Ruckinge Road and Bournewood are flow paths for surface water.  Sewers  Speringbrook Sewer  FMfSW (deep) identifies the following roads as pathways Bourne Lane, Bournewood, Cock Lane, Ruckinge Road and the Lane	Surface water flooded the road at Ruckinge Road (2010) and Bournewood (2012).  In 2010, there is a recorded incider of sewer flooding.  The Second Speringbrook Sewer overtopped at the upstream inlet to the culverted length under the road This resulted in flooding of at least one house adjacent to the culvert. One property in Cock Lane also flooded.  FMfSW (deep) correlates with historical surface water flooding in Bournewood.
B: Hamstreet (south)	Heavy rainfall resulting in surface water run off and overloaded sewers. Surface water (blocked drains/ gullies) Groundwater Fluvial	Bunkley Meadow, Cock Lane and Marsh Road Sewers  2nd Speringbrook Viaduct Arm (RMIDB Drain), Speringbrook Sewer, Unnamed Drain  FMfSW (deep) identifies the following as pathways Second Spering Sewer, Cock Lane and Ham Street Footbal Grounds	Bunkley Meadow is described as a problem area - a watercourse and pumping station located here. There are recorded incidents of flooding from a local watercourse of the footpath, road and within the pumping station.  In 2010, sewer flooding was caused by hydraulic overload and an overloaded pumping station, the curtilage of one property was afffected.  A blocked gully caused flooding to Cock Lane (2009) and Marsh Road (2010).
C: Other (isolated incidents in the area)	Fluvial	Woodchurch	A COW at Woodchurch unless maintained has been known to cause problems.

