

Asset Management in Highways

Forward Planned Works Programme

2019/20-2020/21



Introduction

This is the programme of planned highway maintenance works which we intend to carry out on the highway network during 2019/20-2020/21, and supersedes the interim programme covering the first part of 2019/20 which we published in April 2019. However, it remains a live document: as it is being published some months into 2019/20 some schemes will already have been delivered, whilst for some asset groups the programme for 2020/21 is still being developed. It is thus likely that we will publish an updated version of this programme later this year.

This programme is subject to regular review and may change for a number of reasons including budget allocation, contract rate changes, and to reflect KCC's changing priorities. The programme and extent of individual sites within the programme may also be revised following engineering assessment during the design phase.

The forward planned works programmes are put together based on the approach to asset management set out in our documents [Developing our Approach to Asset Management in Highways](#) and [A Risk Based Approach - Service Level Risk Assessments](#).

A further programme, covering in outline the maintenance work which we intend to carry out on the highway network during 2021/22-2023/24, will be published later this year. Both the Year One to Two and Year Three to Five programmes will be reviewed and re-published annually.

Kent County Council has significantly increased its planned maintenance budget for the next three years, for example doubling road maintenance, trebling footway maintenance and a significant increase in crash barrier renewal.

Notes on the information included in our programme

Roads

- Surface preservation involves repairing and treating roads to improve their quality and extend their useful life before they need renewing or reconstructing. We may apply one or more coats of a cold-laid surface treatment material (micro surfacing) or of bitumen and chippings (surface dressing), or we may recycle and re-lay the existing surface material before applying a surface treatment (retread).
- Road renewal describes the range of responses we may use when the surface or sub-surface layers of a road have deteriorated to the point that they need to be replaced. On asphalt roads where only the top layers are affected, we remove the existing surface by machine, a process known as milling. We then use a mechanical sweeper to ensure that the prepared surface is free from dust and debris. Finally, we lay the new surfacing material in either one or two layers using a machine called a paver, and compact the new surface with a roller. Where lower levels

of a road have also deteriorated, we may fully or partially reconstruct the road. On concrete roads we may carry out localised concrete repairs or replace full sections, and only overlay them with asphalt when this is necessary for engineering reasons.

- Retexturing is carried out where surveys indicate that the texture of the road is starting to deteriorate, and involves treating the road surface to restore its texture and grip.

Footways

- Footway preservation is used where small defects are starting to show, and we wish to treat them now to seal the surface, preventing further deterioration and restoring the condition and appearance of the footway. It involves preparing the footway surface and applying by hand or two coats of a cold-laid surface treatment material, a process known as slurry sealing.
- Footway reconstruction involves removing and replacing at least the walking surface and sometimes deeper layers of the footway, and may include renewing kerbs and/or edgings. In some locations this may mean we are renewing damaged paving slabs or replacing slabs with an asphalt surface.

For more information about how we look after roads and footways, please visit [Kent County Council's website](#).

Street Lighting

- This year we reached a major milestone in our ambitious LED street light conversion programme. Work started on the £40 million scheme in March 2016 and in May 2019 reached its original target of 118,000 lights converted. While the main project is completed, we are continuing work which aims to complete the conversion of all remaining KCC-owned lights by winter 2019. This work includes lights that have just been adopted by KCC or where there has been engineering challenges and access issues to our equipment.
- The replacement of KCC's concrete street lighting columns was substantially completed at the end of July 2019 with the exception of those where there are access issues. These are being re-programmed and it is anticipated that these will be completed by the end of October 2019.
- Generally, the replacement of street lighting columns is based on the results of structural testing which is carried out each year. Due to the high numbers that are likely to be replaced across many locations, it is not possible to provide a detailed schedule of works.
- In 2019, illuminated signs are being reviewed with a view to de-illuminating signs where permissible and replacing those that are required to remain illuminated but have failed a structural test. Electrical testing of illuminated signs is also being carried out and remedial work will be carried out where electrical defects are identified.

Traffic Signals

- The need for planned work on traffic signals is based on an assessment of the equipment's age and the number of faults which have been reported during the past two years.
- The programme of planned work on traffic signals can be affected by the availability of spare parts, particularly for older equipment which is no longer manufactured.
- Work on traffic signals near development sites has not been included in the assessment as they may need alteration as part of the adjacent works.

Soft Landscape

- Grass cutting: urban areas are cut with a ride-on mower/trimmer. The cuttings are not cleared.
- Swathe cutting: a 0.9m wide strip next to the road or footway is cut with a tractor and flail. The cuttings are not cleared.
- Visibility cutting: the full width of grassed areas at junctions and bends is cut with a tractor and flail to maintain visibility.
- Shrub bed maintenance: the timing of this work depends on location. Beds are weeded and pruned, and self-seeded trees and litter removed.
- Urban hedge cutting: ornamental hedges are cut with a hedge cutter, and weeds, self-seeded trees and litter removed.
- Rural hedge cutting: the side of the hedge which faces towards the highway is cut with a tractor and flail cutter.
- Weed spraying: overgrown areas are sprayed with herbicide that kills all green vegetation. Weeds are swept up by the District Council.

Structures

- In addition to the works included in the programme, which covers the most significant and substantial works programmed for 2019/20 and 2020/21, we will be continuing to develop our programme of planned works and carrying out reactive works in response to enquiries and our ongoing programme of inspections.

Crash Barriers

- In addition to the works included in the programme, accident damage repairs are prioritised and carried out as either scheduled repair programmes or as separate urgent works.

Planned Works Programme – 2019/20-2020/21

Last update: August 2019

Last review: August 2019

ALL DISTRICTS							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
High Speed Roads - various locations			All Districts	Lines & road studs	Areas of lining which are above 50% faded are to be refreshed and missing road stud inserts replaced	Extents to be determined	Condition survey
Non-High Speed Roads - various locations			All Districts	Lines & road studs	Areas of lining which are above 50% faded are to be refreshed and missing road stud inserts replaced	Extents to be determined, Junctions and pedestrian crossings to be prioritised	Condition survey and local needs
Grassed areas - various locations			All Districts	Soft Landscape	Swathe cutting - see notes	Various	Routine maintenance: once a year
Grassed areas - various locations			All Districts	Soft Landscape	Visibility cutting - see notes	Various	Routine maintenance: three times a year
Rural hedges - various locations			All Districts	Soft Landscape	Rural hedge cutting - see notes	Various	Routine maintenance: once a year
Shrub beds - various locations			All Districts	Soft Landscape	Shrub bed maintenance - see notes	Various	Routine maintenance: once a year
Urban grassed areas - various locations			All Districts	Soft Landscape	Grass cutting - see notes	Various	Routine maintenance: six times a year
Urban hedges - various locations			All Districts	Soft Landscape	Urban hedge cutting - see notes	Various	Routine maintenance: once a year

ALL DISTRICTS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Various areas			All Districts	Soft Landscape	Weed spraying - see notes	Various	Routine maintenance: once a year
Various roads			All Districts	Street Lighting	Street lighting column replacement - see notes	Various locations	Structural testing
Various roads			All Districts	Street Lighting	De-illumination of illuminated signs - see notes	Various locations	Review of legal requirements
Various roads			All Districts	Street Lighting	Illuminated sign column replacement - see notes	Various locations	Structural testing
Various roads			All Districts	Street Lighting	Remedial work to illuminated signs - see notes	Various locations	Electrical testing

ASHFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ashford Road	A28	Bethersden	Ashford	Road	Road renewal	From Bull Lane to Standard Lane	Condition survey
Acton Lane		Wittersham	Ashford	Road	Surface preservation	From Stone Corner to stream (100 metres before Rushgreen House)	Condition survey
Appledore Road/Bench Hill/Woodchurch Road		Kenardington	Ashford	Road	Surface preservation	Between B2067 and School Road	Condition survey
Ash Hill		Ruckinge	Ashford	Road	Surface preservation	Mid section to cattle grid	Condition survey
Ashford Road	A28	Chilham	Ashford	Road	Surface preservation	From East Stour Farm to 'The Beeches'	Local needs
Ashford Road	A28	Chilham	Ashford	Road	Road renewal	Approximately from East Stour Farm to The Beeches	Condition survey/local needs
Benenden Road		Biddenden	Ashford	Road	Surface preservation	From Woolpack Corner to Tenterden Road	Local needs
Bethersden Road		Smarden	Ashford	Road	Surface preservation	From Biddenden Road to Little Langley Farm	Condition survey
Biddenden Road		Smarden	Ashford	Road	Surface preservation	From Bethersden Road to property 'West View'	Condition survey
Brabourne Road		Wye	Ashford	Road	Surface preservation	From Marse Road To Hampton Lane	Condition survey
Bromley Green Road		Ruckinge	Ashford	Road	Surface preservation	Extents to be determined	Condition survey
Bugglesden Road		Tenterden	Ashford	Road	Road reconstruction (recycling)	Whole length	Condition survey
Bunkley Meadow		Hamstreet	Ashford	Drainage	Re-route rising main to a more suitable location	Footpath link	Customer enquiries
Calleywell Lane		Aldington	Ashford	Road	Surface preservation	Whole length	Condition survey

ASHFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Canterbury Road		Brabourne Lees	Ashford	Road	Surface preservation	From Canterbury Road to Pound Lane	Condition survey
Canterbury Road	A28	Kennington	Ashford	Road	Road renewal	From George Williams Way to Bybrook Road	Condition survey/local needs
Canterbury Road		Chilham	Ashford	Road	Surface preservation	From Green Lane to wooded section	Condition survey
Canterbury Road		Brabourne Lees	Ashford	Road	Surface preservation	From Pound Lane to Manor Pound Lane	Condition survey
Chart Road		Great Chart with Singleton	Ashford	Structures	Bridge refurbishment / strengthening	Bucksford Bridge (KCC Structure No. 13)	Condition survey
Eastern Avenue		Ashford	Ashford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Faversham Road	A251	Challock	Ashford	Road	Surface preservation	From Pested Lane to Challock crossroads	Condition survey
Flood Street		Mersham	Ashford	Structures	Bridge strengthening / reconstruction	Mersham Forstal (KCC Structure No. 131)	Condition survey
Front Road		Woodchurch	Ashford	Structures	Bridge strengthening	Stone Bridge (KCC Structure No. 196)	Condition survey
Godinton Road		Ashford	Ashford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Hamstreet Road		Bromley Green	Ashford	Road	Retexturing	Crossroads at Bromley Green and Sugarloaf	Road grip survey
Heath Road		Appledore	Ashford	Road	Surface preservation	From School Road to The Street	Condition survey
High Halden Road		Biddenden	Ashford	Road	Surface preservation	Extents to be determined	Condition survey
Hornash Lane		Shadoxhurst	Ashford	Road	Surface preservation	Extents to be determined	Condition survey

ASHFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Hythe Road		Various	Ashford	Road	Surface preservation	From Bockham Lane to Ashford/Folkestone & Hythe boundary (various sections)	Condition survey
Hythe Road	A292	Willesborough	Ashford	Road	Road renewal	From Church Road to M20 London bound on slip	Condition survey
Hythe Road		Ashford	Ashford	Structures	Structural painting	Hythe Road Footbridge (KCC Structure No. 2594 over railway)	Condition survey
Hythe Road	A292	Ashford	Ashford	Traffic Signals	Signal crossing refurbishment	Near Star Road	Annual review of equipment age, specification and fault rate
James Street		Ashford	Ashford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Kennington Road	A2070	Willesborough	Ashford	Road	Road renewal	William Harvey Hospital to M20 Junction 10	Condition survey/local needs
Kennington Road	A2070	Willesborough	Ashford	Road	Road renewal	From Quest to the rail bridge past Julie Rose Stadium	Local needs
Knoll Hill		Aldington	Ashford	Road	Surface preservation	From Boat Lane to Roman Road	Condition survey
Knoll Hill		Aldington	Ashford	Road	Surface preservation	From Knoll Hill to Boat Lane	Condition survey
Lower Lees Road		Chilham	Ashford	Road	Surface preservation	From Cobbs Hill to Shalmsford Road	Condition survey
Mace Lane	A292	Ashford	Ashford	Structures	Infilling	Mace Lane Pedestrian Subway (KCC Structure No. 3009) under road	Condition survey
Maidstone Road	A20	Ashford	Ashford	Road	Road renewal	Extents to be determined	Condition survey

ASHFORD

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Maidstone Road North Of Drovers Roundabout	A20		Ashford	Road	Road renewal	Extents to be determined	Condition survey
New Road Hill/Forge Hill		Aldington	Ashford	Road	Surface preservation	From Cherry Orchard Lane to Mill Lane	Condition survey
Nortons Lane		Tenterden	Ashford	Road	Road reconstruction (recycling)	From The Grange to the junction	Condition survey
Perrywood Road		Perrywood	Ashford	Road	Surface preservation	From Shottenden Road to Fishes Street Road	Condition survey
Pook Lane		Biddenden	Ashford	Road	Surface preservation	Extents to be determined	Condition survey
Rolvenden Road	A28	Tenterden	Ashford	Road	Surface preservation	From Halden Road to Cranbrook Road	Condition survey
Ruckinge Road		Ham Street	Ashford	Road	Surface preservation	From top of hill to start of woods	Condition survey
Ruckinge Road		Ham Street	Ashford	Road	Surface preservation	From Ruckinge Road to The Street	Condition survey
Scots Lane		Brabourne Lees	Ashford	Road	Surface preservation	From Canterbury Road to Fiddling Lane	Condition survey
Smallhythe Road		Tenterden	Ashford	Road	Surface preservation	From red high friction surfacing/30 mph speed limit signs to nursery entrance	Condition survey
Smallhythe Road		Tenterden	Ashford	Road	Surface preservation	Through woods	Condition survey
Susans Hill		Woodchurch	Ashford	Road	Surface preservation	From Little Robhurst to Bethersden Road	Condition survey
Tenterden Road		Rolvenden	Ashford	Road	Surface preservation	From Halden Lane to Mounts Lane	Condition survey
Tenterden Road	A262	Biddenden	Ashford	Road	Road renewal	Extents to be determined	Condition survey
Warehorne Road		Warehorne	Ashford	Road	Surface preservation	Wooded section	Condition survey
Warehorne Road	B2067	Warehorne	Ashford	Road	Road renewal	Extents to be determined	Condition survey
Wassall Lane		Rolvenden	Ashford	Road	Surface preservation	From A28 to Frog Lane	Condition survey

ASHFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
West Cross	A28	Tenterden	Ashford	Traffic Signals	Signal junction refurbishment	At the junction with B2082 Small Hythe Road	Annual review of equipment age, specification and fault rate
Western Road		Ashford	Ashford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Willesborough Road		Ashford	Ashford	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
Wissenden Lane		Bethersden	Ashford	Road	Surface preservation	From Tudesnoad Lane to Tudesnoad Lane	Condition survey
Wissenden Lane/ School Road/ Orchard Field		Bethersden	Ashford	Drainage	Full survey to be undertaken and scheme developed	Whole roads	Customer enquiries
Woodchurch Road		Kenardington	Ashford	Road	Surface preservation	Two sections through woods	Condition survey

CANTERBURY

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ashford Road	A28	Chartham	Canterbury	Road	Road renewal	Extents to be determined	Local needs
Bekesbourne Hill		Bekesbourne	Canterbury	Road	Surface preservation	From entrance to Bekesbourne Station to Bekesbourne Lane	Condition survey
Bekesbourne Lane		Bekesbourne	Canterbury	Road	Surface preservation	From Little Barton Farm to Palmsted Wood	Condition survey
Boyden Gate Hill		Chislet	Canterbury	Road	Surface preservation	From Chapel Lane to Old Tree Lane	Condition survey
Broad Street		Canterbury	Canterbury	Road	Surface preservation	Whole length one way	Condition survey
Canterbury Road	A291	Herne	Canterbury	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Canterbury Road	B2205	Herne Bay	Canterbury	Road	Road renewal	From High Street to Eddington Lane	Condition survey
Canterbury Road	A28	Chartham	Canterbury	Road	Road renewal	From Howfield Lane to A2 Interchange	Resilient Highway Network
Canterbury Road	A260	Barham	Canterbury	Road	Road renewal	From Clints Lane to Agerster Lane	Condition survey
Castle Road		Whitstable	Canterbury	Road	Surface preservation	From Summerfield Avenue to Strangford Road	Condition survey
Chalkpit Hill / School Lane		Bekesbourne	Canterbury	Road	Surface preservation	From Station Road to Addisham Road	Condition survey
Church Lane		Chislet	Canterbury	Road	Surface preservation	Extents to be determined	Condition survey
Church Lane		Chislet	Canterbury	Road	Surface preservation	From Hollow Street to past Hollow Road	Condition survey
Church Street		Whitstable	Canterbury	Road	Surface preservation	From Thanet Way to Summerfield Avenue	Condition survey
Denstead Lane		Chartham	Canterbury	Road	Surface preservation	From Bigbury Lane to A2 Dover Road	Condition survey

CANTERBURY

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Faversham Road		Whitstable	Canterbury	Road	Road reconstruction (recycling)	From The Sportsman public house to Clee Hill Drive	Condition survey
Fox Lane		Selling	Canterbury	Drainage	Full survey to be undertaken and scheme to be developed	Under railway bridge	Customer enquiries
Gorse Lane		Herne	Canterbury	Footway	Footway preservation	Entire length	Identified by survey
Grimshill Road		Whitstable	Canterbury	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Grove Ferry Road		Chislet/ Wickambreaux	Canterbury	Structures	Re-waterproofing	Grove Ferry Bridge (KCC Structure No. 439) over River Great Stour	Condition survey
Grove Road			Canterbury	Road	Surface preservation	Extents to be determined	Condition survey
Hardres Court Road		Lower Hardres	Canterbury	Road	Surface preservation	From Faussett Hill to Butts Meadow and from Bow Hill to The Manor House	Condition survey
Harwich Street		Whitstable	Canterbury	Footway	Footway renewal	Entire length	Identified by survey
High Street	B2205	Herne Bay	Canterbury	Structures	Refurbishment / infilling	Herne Bay Cellars (KCC Structure No. 8700) between Richmond Street and Beach Street	Condition survey
High Street	B2205	Herne Bay	Canterbury	Road	Road renewal	Between Canterbury Road and Station Road	Condition survey
High Street	B2205	Herne Bay	Canterbury	Road	Road renewal	Canterbury Road and Station Road	Condition survey
Hillview Road		Whitstable	Canterbury	Footway	Footway renewal	Entire length	Identified by survey
Island Road	A28	Sturry	Canterbury	Road	Road renewal	From level crossing to Redcot Lane	Local needs
Kingsmead Road	B2248	Canterbury	Canterbury	Road	Road renewal	Extents to be determined	Condition survey

CANTERBURY

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Kingswood		Barham / Kingston	Canterbury	Road	Surface preservation	Whole lane, junction to junction	Condition survey
London Road		Canterbury	Canterbury	Footway	Footway renewal	Entire length	Identified by survey
Marley Lane		Kingston	Canterbury	Structures	Strengthen embankment / extend retaining wall	Adjacent to Marley Lane Retaining Wall (KCC Structure No. 6956) outside Marley Farm	Partial collapse
Maypole Road /Hoath Road		Hoath	Canterbury	Road	Surface preservation	Section 1: Maypole Lane To Church Road Section 2: Bend At Rushbourne Manor	Condition survey
Mayton Lane		Broad Oak	Canterbury	Drainage	Full survey to be undertaken and scheme developed	Near Golden Lion public house	Customer enquiries
Military Road, Canterbury	A28		Canterbury	Traffic Signals	Signal crossing refurbishment	Near Old Ruttington Lane	Annual review of equipment age, specification and fault rate
Mill Lane		Bridge	Canterbury	Road	Surface preservation	From Mill Terrace to Bridgeford Way	Condition survey
Moat Lane		Fordwich	Canterbury	Road	Surface preservation	From Stodmarsh Road to Sandpit Woods	Condition survey
Nackington Road		Lower Hardres	Canterbury	Road	Surface preservation	By the hospital	Condition survey
New Dover Road		Canterbury	Canterbury	Road	Surface preservation	Between Barton Road and Church Hill Road	Condition survey
Old Thanet Way	A2990	Chestfield	Canterbury	Drainage	Reconstruct kerb inlet gullies	Area near MacDonald's roundabout	Risk assessment
Palmars Cross Hill		Rough Common	Canterbury	Road	Road renewal	Extents to be determined	Condition survey

CANTERBURY

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Penny Pot Lane		Godmersham	Canterbury	Road	Surface preservation	From Mystole Lane to Pennypot Wood	Condition survey
Pond Lane		Womenswold	Canterbury	Road	Road reconstruction (recycling)	Extents to be determined	Condition survey
Reeves Way		Chestfield	Canterbury	Structures	Preventative maintenance to corrugated steel culvert	Reeves Way Culvert (KCC Structure No. 1181) carrying Swalecliffe Brook under road	Condition survey
Reservoir Road		Whitstable	Canterbury	Footway	Footway renewal	Entire length	Identified by survey
Richmond Road		Whitstable	Canterbury	Footway	Footway preservation	Entire length	Identified by survey
Rosemary Gardens		Whitstable	Canterbury	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sea Street	B2205	Herne Bay	Canterbury	Road	Road renewal	From Greenhill Bridge to Sunnyhill Road	Local needs
St George's Place	A257	Canterbury	Canterbury	Road	Road renewal	Extents to be determined	Condition survey
St George's Place	A257	Canterbury	Canterbury	Traffic Signals	Signal crossing refurbishment	At crossing	Annual review of equipment age, specification and fault rate
St Stephen's Hill		Canterbury	Canterbury	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Thanet Way	A299	Herne & Broomfield / Chislet	Canterbury	Crash barriers	Upgrade tensioned corrugated beam (TCB) safety fencing	Various sections between Eddington Interchange and Canterbury CC boundary (works continue into Thanet DC Area)	Condition survey

CANTERBURY

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Thanet Way	A299	Chislet	Canterbury	Structures	Preventative maintenance to corrugated steel culvert	North Stream Culvert (KCC Structure No. 358) carrying watercourse under road.	Condition survey
Thanet Way	A299	Whitstable. Chestfield	Canterbury	Structures	Preventative maintenance to corrugated steel culvert	Bogshole Culvert (KCC Structure No.9032) carrying watercourse alongside Thanet Way and under Convicts Wood Overbridge	Condition survey
Thanet Way	A299	Chislet	Canterbury	Structures	Culvert strengthening	Wantsum culvert (KCC Structure No. 275) carrying River Wantsum under road (also listed under Thanet District)	Condition survey
Tower Parade		Whitstable	Canterbury	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Vauxhall Road			Canterbury	Road	Road renewal	Extents to be determined	Condition survey
Western Esplanade		Herne Bay	Canterbury	Road	Surface preservation	From Lane End to Hampton Pier Avenue	Condition survey
Whitstable Road	A290	Canterbury	Canterbury	Road	Road renewal	Junction with Forty Acres Road	Local needs
Wingham Road	A257	Littlebourne / Ickham and Well	Canterbury	Structures	Structural painting	Littlebourne bridge (KCC Structure No. 185)	Condition survey
Woods Hill		Waltham	Canterbury	Road	Surface preservation	From Richdore Road to Ashenfield Road	Condition survey

DARTFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Barn End Lane		Wilmington	Dartford	Footway	Footway preservation	From High Road to Goss Hill	Identified by survey
Bob Dunn Way	A206	Dartford	Dartford	Road	Road renewal	Extents to be determined	Condition survey
Bob Dunn Way	A206	Dartford	Dartford	Structures	Preventative maintenance to corrugated steel culvert	Stanham River Culvert (KCC Structure No. 2686) under road	Condition survey
Bob Dunn Way	A206	Dartford	Dartford	Structures	2020/21	Fresh Marsh Drain Culvert (KCC Structure No. 2688) carrying watercourse under road	Condition survey
Brewers Field		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey
Broad Lane		Wilmington	Dartford	Footway	Footway preservation	From Common Lane to approximately outside the Evangelical Free Church	Identified by survey
Burnham Road		Dartford	Dartford	Traffic Signals	Signal crossing renewal	Near Priory Road	Annual review of equipment age, specification and fault rate
Chapel Place		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey
Clement Street		Sutton-at-Hone and Hawley	Dartford	Road	Surface preservation	From bridge over M25 to Goss Hill	Condition survey
Crayford Road	A207	Dartford	Dartford	Road	Road renewal	Extents to be determined	Condition survey
Crossways Boulevard	A206	Dartford	Dartford	Road	Road renewal	Extents to be determined	Condition survey
Darenth Road		Dartford	Dartford	Road	Surface preservation	From A225 East Hill to Dene Road	Condition survey
East Hill	A226	Dartford	Dartford	Road	Road renewal	Extents to be determined	Local needs
Gerdview Drive		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey

DARTFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Hartshaw		Longfield	Dartford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Havelock Road		Dartford	Dartford	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Joydens Wood Road		Bexley	Dartford	Road	Surface preservation	From Summerhouse Drive to Tile Kiln Lane	Condition survey
Ladywood Road		Darenth	Dartford	Road	Surface preservation	Whole road	Condition survey
Lawford Gardens		Dartford	Dartford	Footway	Footway renewal	Entire length	Identified by survey
London Road		Greenhithe	Dartford	Drainage	Replace/ upgrade existing drainage system	From outside No. 16 to outside No. 41a	Risk assessment
London Road		Swanscombe and Greenhithe	Dartford	Road	Road renewal	From St Clements Road to Knockhall Road	Local needs
Manor Way		Swanscombe	Dartford	Drainage	Full survey to be undertaken and scheme developed	Outside MJD Group	Customer enquiries
Marcet Road		Dartford	Dartford	Footway	Footway renewal	Entire length	Identified by survey
Marsh Street North		Dartford	Dartford	Drainage	Full survey to be undertaken and scheme developed	On Marsh Street North and the two roundabouts: south - Bob Dunn Way and north one	Customer enquiries
Mayors Lane		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey
Meadow Walk		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey
Mill Pond Road		Dartford	Dartford	Structures	Structural painting	Phoenix Mill Bridge (KCC Structure No. 53A) over River Darent	Condition survey
Milton Road			Dartford	Drainage	8 metre soakaway	In the lagoon in Swanscombe Heritage Park	Risk assessment

DARTFORD							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Milton Road		Swanscombe	Dartford	Road	Surface preservation	From Church Road to Sweyne Road	Condition survey
Milton Street		Swanscombe	Dartford	Drainage	Review of any outstanding issues following previous works	Near the junction with Milton Road	Customer enquiries
New Barn Road		Longfield	Dartford	Road	Road renewal	Extents to be determined	Condition survey
Old Bexley Lane	A2018	Bexley	Dartford	Road	Road renewal	Extents to be determined	Condition survey
Orchard Close		Longfield	Dartford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Princes Road		Dartford	Dartford	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Princes Road	B2174	Dartford	Dartford	Structures	Structural painting	Access ramps to Princes Road Footbridge (KCC Structure No. 499)	Condition survey
Rayford Close		Dartford	Dartford	Footway	Footway renewal	Entire length	Identified by survey
Rectory Meadow		Southfleet	Dartford	Road	Surface preservation	Service road and all spurs, including Monks Walk	Condition survey
Rowlatt Road		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey
Sandpit Road		Dartford	Dartford	Footway	Footway renewal	Entire length	Identified by survey
Sandpit Road		Dartford	Dartford	Road	Road reconstruction	Whole length	Condition survey
Sandpit Road		Dartford	Dartford	Road	Road renewal	Whole length	Condition survey
Southfleet Avenue		Longfield	Dartford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Stanhope Road		Swanscombe	Dartford	Drainage	Full survey to be undertaken and scheme developed	Various locations	Customer enquiries

DARTFORD

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
The Close		Longfield	Dartford	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Whitehead Close		Wilmington	Dartford	Footway	Footway preservation	Entire length	Identified by survey

DOVER

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ackholt Road		Aylesham	Dover	Road	Surface preservation	From bridge/ Bell Grove to Spinney Lane	Condition survey
Adisham Road		Aylesham	Dover	Road	Road renewal	From Spinney Lane to Cooting Road	Condition survey
Astor Avenue		Dover	Dover	Traffic Signals	Signal crossing refurbishment	Near South Road	Annual review of equipment age, specification and fault rate
Barfreestone Road		Shepherdswell With Coldred	Dover	Road	Surface preservation	From Eythorne Road to Long Lane	Condition survey
Barville Road		Eythorne	Dover	Road	Surface preservation	From Pike Road to A256	Condition survey
Biggin Street (Phase 2)		Dover	Dover	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Broad Lane		Betteshanger	Dover	Road	Surface preservation	From Northbourne Road to North Stream Brook	Condition survey
Canterbury Road	A257	Lydden	Dover	Road	Retexturing	At St Mary The Virgin Church	Road grip survey
Canterbury Road	A260	Denton	Dover	Road	Road renewal	From Clints Lane to Agester Lane	Condition survey
Chapel Lane		Ashley	Dover	Road	Surface preservation	From Homestead Lane /public house to Waldershare Road	Condition survey
Deal Road	A258	St Margaret's at Cliffe	Dover	Road	Road renewal	Extents to be determined	Local needs
Deal Road	A258	St Margaret's at Cliffe	Dover	Road	Road renewal	From Swingate Inn to Dover Road	Condition survey
Dover Road		Walmer	Dover	Drainage	Install and connect new 1.8 metre x 5.5 metre soakaway	Opposite Nos. 281 to 283	Risk assessment
Dover Road	A258	Ringwould	Dover	Road	Road renewal	Extents to be determined	Local needs

DOVER							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Dover Road	A258	Ringwould	Dover	Road	Road renewal	From Animal Inn to Queens Rise	Condition survey
Elms Vale Road		Dover	Dover	Road	Road renewal	From Kings Road to Folkestone Road	Condition survey
Folkestone Road		Dover	Dover	Road	Surface preservation	From station bridge to Elms Vale Road roundabout	Condition survey
Folkestone Road		Dover	Dover	Road	Surface preservation	From Shakespeare Road to No. 413 Folkestone Rd	Condition survey
Folkestone Road	B2011	Dover	Dover	Traffic Signals	Signal crossing renewal	Near Maxton Road	Annual review of equipment age, specification and fault rate
Guilford Road		Sandwich	Dover	Structures	Preventative maintenance to corrugated steel culvert	Great Downs Culvert (KCC Structure No. 686) carrying watercourse under road.	Condition survey
High Street		Deal	Dover	Drainage	Replace all gully pots with new gully pots including pedestrian gratings	From the junction of South Street to the junction of Park Street	Risk assessment
High Street		Dover	Dover	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
High Street	A256	Dover	Dover	Traffic Signals	Signal junction refurbishment	At the junction with Bridge Street / Tower Hamlets	Annual review of equipment age, specification and fault rate
James Hall Gardens		Walmer	Dover	Footway	Footway renewal	Entire length	Identified by survey

DOVER							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ladywell/ Park Street	B2245		Dover	Road	Road renewal	From High Street to Maison Dieu	Condition survey
London Road	A258	Deal	Dover	Road	Road renewal	From Grange Road to Beechwood Avenue	Condition survey
London Road	A258	Deal	Dover	Road	Road renewal	From Warden House Mews to St Leonards Road	Condition survey
London Road	A258	Deal	Dover	Road	Road renewal	From Mongeham Road to Sholden New Road	Condition survey
Lorne Road		Dover	Dover	Structures	Structural repairs	Lorne Road Culvert (KCC Structure No. 1427) carrying River Dour under road	Condition survey
Lower Mill Lane junction with Willow Woods Road	C231 j/w C321	Northbourne	Dover	Road	Surface preservation	From Willow Woods Road to Northbourne Lane	Condition survey
Mangers Lane		Dover	Dover	Road	Surface preservation	From Crapple Hill to Managers Lane	Condition survey
New Dover Road		Capel-Le-Ferne	Dover	Road	Surface preservation	From A20 to Winehouse Road	Condition survey
Northbourne Road		Betteshanger	Dover	Road	Surface preservation	From Broad Lane to Northbourne Lane	Condition survey
Pike Road		Tilmanstone	Dover	Road	Surface preservation	From Thornton Road to Industrial Estate	Condition survey
Pike Road		Tilmanstone	Dover	Road	Surface preservation	From Thornton Road to Lower Street	Condition survey
Pineham Road		Guston, Pineham	Dover	Road	Surface preservation	From Guston Village to Pineham Village (extents to be confirmed)	Condition survey
Ramsgate Road		Sandwich	Dover	Structures	Bridge repairs	Sandwich Toll Bridge (KCC Structure No. 1693)	Condition survey

DOVER

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Roman Road		Staple/Ash	Dover	Road	Surface preservation	From Wingham Country Market to Pedding Hill	Condition survey
Roosevelt Road/Green Road		Dover	Dover	Road	Surface preservation	From Old Park Hill to Hudson Close surface change	Condition survey
Rubberies Wood Road	C201	Nonington	Dover	Road	Surface preservation	From Frogham to railway	Condition survey
Sandwich Bypass	A256	Ash/Sandwich	Dover	Structures	Preventative maintenance to corrugated steel culvert	A256 North Poulders Stream Culvert (KCC Structure No.1822) carrying watercourse under road.	Condition survey
St Radigunds Road		Dover	Dover	Road	Surface preservation	From White Cliffs Primary College to No. 273	Condition survey
Stourmouth Road		Preston	Dover	Road	Surface preservation	From 40 mph/60 mph speed limit signs to Stour Bridge	Condition survey
Straight Mile		Betteshanger	Dover	Road	Surface preservation	From the preparatory school to Northbourne Road	Condition survey
The Street (Goretop Lane)		Worth	Dover	Structures	Bridge strengthening	Brewers Bridge (KCC Structure No. 363)	Partial Collapse
Woodnesborough Road (Moat Sole)		Sandwich	Dover	Road	Surface preservation	From Co-op roundabout to Town Wall	Condition survey

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Aldington Road		Lympne	Folkestone & Hythe	Road	Surface preservation	From Lympne Hill to A261	Condition survey
Ashentree Lane		Brookland	Folkestone & Hythe	Road	Surface preservation	From Hook Wall to Narrowbush Lane	Condition survey
Ashford Road		Brenzett	Folkestone & Hythe	Road	Surface preservation	From A2070 to Brenzett	Condition survey
Bunkers Hill		Wingmore	Folkestone & Hythe	Drainage	Further Investigation	Near Ivy Cottage	Risk assessment
Caldecott Lane		Lydd	Folkestone & Hythe	Road	Surface preservation	From Romney Road to level crossing	Condition survey
Canterbury Road		Hawkinge	Folkestone & Hythe	Drainage	2 new soakaways and pond clearance	In the grounds of Mill Gate Farm	Risk assessment
Canterbury Road		Folkestone	Folkestone & Hythe	Drainage	Review of any outstanding issues following previous works	South of roundabout	Customer enquiries
Canterbury Road		Wingmore	Folkestone & Hythe	Drainage	Nailbourne river - upgrade and improve system	Near the junction with Straight Hill	Risk assessment
Canterbury Road		Swingfield Hawkinge	Folkestone & Hythe	Road	Surface preservation	From Densole Lane to Spitfire Way	Condition survey
Canterbury Road	A260	Densole	Folkestone & Hythe	Road	Road renewal	From north of Black Horse Farm Caravan Park to Black Horse public house	Condition survey
Cheriton High Street		Cheriton	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	At junction with Stanley Road	Customer enquiries

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Cheriton High Street	A20	Cheriton	Folkestone & Hythe	Traffic Signals	Signal crossing renewal	Near Marler Road	Annual review of equipment age, specification and fault rate
Cheriton Road	A259	Folkestone	Folkestone & Hythe	Road	Road renewal	From Cheriton Road to Shorncliffe Road	Condition survey
Cherry Garden Avenue		Folkestone	Folkestone & Hythe	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Cherry Garden Lane		Folkestone	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
Churchill		Hawkinge	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	Under Alkham Valley Road	Customer enquiries
Corone Close		Cheriton	Folkestone & Hythe	Footway	Footway preservation	Entire length	Identified by survey
Dover Road	A2033	Folkestone	Folkestone & Hythe	Road	Road renewal	From Harbour Way through to Grace Hill roundabout	Condition survey
Dymchurch Road	A259		Folkestone & Hythe	Traffic Signals	Signal crossing renewal	Near Fort Road	Annual review of equipment age, specification and fault rate
Eastbridge Road		Dymchurch / Burmarsh	Folkestone & Hythe	Road	Road reconstruction (recycling)	Extents to be determined	Condition survey
Enbrook Road		Sandgate	Folkestone & Hythe	Drainage	Investigate culverted watercourse	Near the junction of Chichester Road	Risk assessment
Fairway Avenue		Cheriton	Folkestone & Hythe	Footway	Footway preservation	Entire length	Identified by survey

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Foresters Way	A2033	Folkestone	Folkestone & Hythe	Road	Road renewal	Extents to be determined	Condition survey
Foresters Way Bus Lane	A2033	Folkestone	Folkestone & Hythe	Road	Road renewal	From Middleburg Square to Grace Hill	Condition survey
From Newchurch Town Boundary To Eastbridge		Dymchurch	Folkestone & Hythe	Road	Surface preservation	From Eastbridge Road to property 'Merrifields'	Condition survey
Green Lane/Bridge Close		Hythe	Folkestone & Hythe	Structures	Culvert strengthening	Sections of Green Lane Culvert (KCC Structure No. 3413) under Green Lane and Bridge Close	Condition survey
High Minnis		Stelling Minnis, Rhodes Minnis	Folkestone & Hythe	Road	Surface preservation	Between property 'Oak Ridge' to property Woodside Cottage	Condition survey
High Minnis		Stelling Minnis, Rhodes Minnis	Folkestone & Hythe	Road	Surface preservation	From un-named road to Droveway	Condition survey
High Street		New Romney	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	Whole road	Section 19 Flooding Identification
High Street	A259	Dymchurch	Folkestone & Hythe	Road	Road renewal	From Sainsburys Roundabout to north of B2071 Station Road	Condition survey
High Street		Lydd	Folkestone & Hythe	Road	Surface preservation	From Tourney Road to Dennes Lane	Condition survey
High Street	A259	New Romney	Folkestone & Hythe	Road	Road renewal	From Sainsbury's roundabout to north of B2071 Station Road	Condition survey
Hogg Lane		Snargate	Folkestone & Hythe	Road	Road reconstruction (recycling)	Extents to be determined	Condition survey

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Hook Wall		Brookland	Folkestone & Hythe	Structures	Bridge reconstruction	Woolpack Bridge (KCC Structure No. 667) over White Kemp Sewer	Partial collapse
Hope All Saints		St. Mary in the Marsh	Folkestone & Hythe	Road	Road renewal	Extents to be determined	Condition survey
Ivychurch Road		Brenzett/ Ivychurch	Folkestone & Hythe	Road	Surface preservation	From A2070 to 400 metres past Moor Lane	Condition survey
Lane From Junction With Turnagate Cottage		St Mary In The Marsh	Folkestone & Hythe	Road	Surface preservation	From just past Rectory Road to Hope Lane	Condition survey
Lower Wall Road		Burmarsh	Folkestone & Hythe	Road	Surface preservation	From Donkey Street to Aldergate Lane	Condition survey
Lydd Road	A259	New Romney	Folkestone & Hythe	Road	Road renewal	Extents to be determined	Condition survey
Midley Wall		Old Romney	Folkestone & Hythe	Road	Surface preservation	From Ashentree Lane towards Cold Harbour Lane	Condition survey
Mill Road		Hythe	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	Opposite Church	Customer enquiries
Millfields		Hythe	Folkestone & Hythe	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Mockbeggar		Lyminge / Elmsted	Folkestone & Hythe	Road	Surface preservation	From Stone Street to Gate Lane	Condition survey
Narrowbush Lane		Romney Marsh	Folkestone & Hythe	Road	Road reconstruction (recycling)	Extents to be determined	Condition survey
Newchurch Road		St Marys In The Marsh	Folkestone & Hythe	Road	Road reconstruction (recycling)	From Griggors Green Road to Mill Lane	Condition survey
Oak Hill		Folkestone	Folkestone & Hythe	Road	Surface preservation	From Acrise Park Road to Ridge Road	Condition survey

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Pavilion Road	A259	Folkestone	Folkestone & Hythe	Road	Road renewal	From Radnor Park Road 4 way junction to Black Bull Road	Condition survey
Pentvale Close		Cheriton	Folkestone & Hythe	Footway	Footway preservation	Entire length	Identified by survey
Pilgrims Way		Postling	Folkestone & Hythe	Road	Surface preservation	From 100 metres past Staple Street to Stone Street	Condition survey
Radnor Park Road	A259	Folkestone	Folkestone & Hythe	Road	Road renewal	From Black Bull Road to 4-way junction with Pavilion Road	Condition survey
Sandgate Road	A2033	Folkestone	Folkestone & Hythe	Road	Road renewal	From Earls Avenue to Castle Hill Avenue	Condition survey
Seabrook Road		Hythe	Folkestone & Hythe	Drainage	Full survey to be undertaken and scheme developed	At the junction with Horn Street	Customer enquiries
Seabrook Road	A259	Hythe	Folkestone & Hythe	Road	Road renewal	Extents to be determined	Condition survey
Shellons Street	A2033	Folkestone	Folkestone & Hythe	Road	Road renewal	Extents to be determined	Condition survey
Southmead Close		Cheriton	Folkestone & Hythe	Footway	Footway preservation	Entire length	Identified by survey
Spitfire Way	A260	Hawkinge	Folkestone & Hythe	Road	Road renewal	Between Canterbury Road and Aerodrome Road	Local needs
St Marys Road (Newchurch Road)		St Marys In The Marsh	Folkestone & Hythe	Road	Road reconstruction (recycling)	From St Mary's Road (crossroads) to 'S' bend	Condition survey
Staple Lane		Postling	Folkestone & Hythe	Road	Surface preservation	From Sandling Lane to The Street	Condition survey
Stone Street	B2068	Stelling Minnis	Folkestone & Hythe	Road	Road renewal	From George Inn to Misling Lane	Condition survey

FOLKESTONE & HYTHE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
The Tram Road	A260	Folkestone	Folkestone & Hythe	Road	Road renewal	From Harbour Street to Harvey Street	Condition survey
Tillery Lane		Ivychurch	Folkestone & Hythe	Structures	Preventative maintenance to corrugated steel culvert	Nashes Culvert (KCC Structure No. 2389) carrying watercourse under road	Condition survey
Wenhams Lane		Ivychurch / Old Romney	Folkestone & Hythe	Structures	Bridge strengthening	Yoakes (KCC Structure No. 709)	Condition survey

GRAVESHAM

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Arnold Close		Meopham	Gravesham	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Blenheim Close		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Bracondale Avenue		Istead Rise	Gravesham	Drainage	Full survey to be undertaken and scheme developed	Whole road including junction With A227	Customer enquiries
Brook Road		Gravesend	Gravesham	Drainage	Full survey to be undertaken and scheme developed	Northern end	Customer enquiries
Cervia Way		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Chalk Road		Gravesend	Gravesham	Road	Surface preservation	From Vicarage Road to Rochester Road	Condition survey
Cheyne Walk		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Cobhambury Road		Cobham	Gravesham	Road	Surface preservation	From Batts Road to the railway bridge	Condition survey
Colewood Drive		Higham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Cornwell Avenue		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Dabbs Place junction with Copt Hall Rd		Cobham	Gravesham	Road	Surface preservation	From Copt Hall Road to Jeskyns Road	Condition survey
Denesway		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Dobson Road		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Dover Road	A261	Gravesend	Gravesham	Road	Road renewal	From Pelham Road South to A226 Thames Way bridge deck	Condition survey
Dover Road East	B261	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Condition survey
Ediva Road		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Edmund Close		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Fairview Drive		Higham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey

GRAVESHAM

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Fairview Gardens		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Ferndown		Vigo	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Gravesend Road		Shorne	Gravesham	Drainage	Full survey to be undertaken and scheme developed	At the junction with Forge Lane	Customer enquiries
Gravesend Road	A226	Shorne	Gravesham	Road	Road renewal	Shorne Cross Roads to Pear Tree Lane	Resilient Highway Network
Grenville Close		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Hadley Close		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Highwoods Close		Higham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Lances Close		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Longfield Road		Meopham	Gravesham	Footway	Footway renewal	From School Close to o/s No. 32 Longfield Road	Identified by survey
Lower Higham Road		Gravesend	Gravesham	Road	Surface preservation	Adjacent to gas fields	Condition survey
Lower Rochester Road		Higham	Gravesham	Road	Surface preservation	From Gore Green Road to Cherry Garden Cottages	Condition survey
Meadfield Road		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Milton Road			Gravesham	Drainage	8 metre soakaway	In the lagoon in Swanscombe Heritage Park	Risk assessment
Nash Street (including Nash Bank)		Gravesend	Gravesham	Road	Surface preservation	Nash Street: whole road. Nash Bank: from A227 to Downs Road	Condition survey
Nursery Road		Meopham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Oak Drive		Higham	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Old Road East	B261	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Condition survey
Old Road West	B261	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Condition survey
Pear Tree Lane		Shorne	Gravesham	Road	Surface preservation	From Tanyards Hill to A226 bridge	Condition survey

GRAVESHAM

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Pelham Road		Gravesend	Gravesham	Road	Road renewal	From Lennox Road to Granville Road	Local needs
Pelham Road South		Gravesend	Gravesham	Road	Road renewal	From Old Road West to Victoria Road	Local needs
Perry Street	B262	Gravesend	Gravesham	Traffic Signals	Signal crossing refurbishment	Near Victoria Road	Annual review of equipment age, specification and fault rate
Read Way		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Sole Street		Meopham	Gravesham	Drainage	Install and connect two soakaways	From the junction of Sole Street and Manor Road to outside No. 41 Manor Road	Risk assessment
Sole Street		Meopham	Gravesham	Drainage	Full survey to be undertaken and scheme developed	Between Manor Road and Gold Street	Customer enquiries
Springhead Road		Northfleet	Gravesham	Road	Retexturing	Circulation of roundabout	Road grip survey
St Hilda's Way		Gravesend	Gravesham	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
St Margarets Crescent			Gravesham	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
St. David's Crescent		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
St. Dunstans Drive		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
St. Francis Road		Harvel	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
St. Georges Crescent		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Stacey Close		Gravesend	Gravesham	Footway	Footway renewal	Entire length	Identified by survey
Thong Lane		Gravesend	Gravesham	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey

GRAVESHAM

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Timberbank		Vigo	Gravesham	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Two Gates Hill		Higham	Gravesham	Road	Surface preservation	From Lower Rochester Road to Medway boundary	Condition survey
Wainscott Bypass	A289	Higham	Gravesham	Road	Road renewal	From M2 To Medway boundary (Phase 1)	Resilient Highway Network
Wainscott Bypass	A289	Higham	Gravesham	Road	Road renewal	From Medway boundary to M2 (Phase 2)	Resilient Highway Network
Warren Road		Cobham	Gravesham	Road	Surface preservation	From Luddesdown Road to Medway Boundary	Condition survey
Warwick Gardens		Meopham	Gravesham	Footway	Footway preservation	Entire length	Identified by survey
Whitehill Road		Meopham	Gravesham	Footway	Footway preservation	From the Street to outside property 'Alfoxton'	Identified by survey
Windsor Road			Gravesham	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Wrangling Lane		Luddesdown	Gravesham	Road	Surface preservation	From Lockyers Hill to end	Condition survey
Wrotham Road	A227	Gravesend	Gravesham	Drainage	Full survey to be undertaken and scheme developed	Next to Nurstead Wood	Customer enquiries
Wrotham Road	A227	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Local needs
Wrotham Road (Phase 1)	A227	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Condition survey
Wrotham Road (Phase 2)	A227	Gravesend	Gravesham	Road	Road renewal	Extents to be determined	Condition survey
Springhead Road	B262	Northfleet	Gravesham	Road	Road renewal	From Cemetery to Springhead roundabout	Condition survey

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Andrew Broughton Way	A249	Maidstone	Maidstone	Road	Road renewal	Between A249 and Square Hill	Condition survey
Ashford Road		Maidstone	Maidstone	Drainage	Full survey to be undertaken and scheme developed	Under railway bridge	Customer enquiries
Ashford Road	A20	Bearsted	Maidstone	Road	Surface preservation	From near junction with Old Mill Road to junction with Roundwell	Condition survey
Ashford Road	A20	Lenham	Maidstone	Road	Surface preservation	From Old Ashford Road to Northdown Close	Condition survey
Beverley Road		Barming	Maidstone	Footway	Footway preservation	Entire length	Identified by survey
Bow Road		Wateringbury	Maidstone	Road	Surface preservation	From the corner after the bridge to Hunt Street	Condition survey
Broadway		Maidstone	Maidstone	Drainage	Full survey to be undertaken and scheme developed	Subway	Customer enquiries
Broadway	A20	Maidstone	Maidstone	Traffic Signals	Signal junction renewal	Junction with bridge	Annual review of equipment age, specification and fault rate
Broomshaw Road		Barming	Maidstone	Footway	Footway preservation	Entire length	Identified by survey
Bunce Court Road		Otterden	Maidstone	Road	Surface preservation	From Otterden Place (Rigshill Road) to Warren Street (Payden Street)	Condition survey
Cambridge Crescent			Maidstone	Soft Landscape	Tree scheme	Various locations	Tree improvement scheme
Charlton Lane		East Sutton	Maidstone	Road	Surface preservation	From Chartway Street to Church Lane	Condition survey

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Church Road and Lakelands		Harrietsham	Maidstone	Drainage	Review of any outstanding issues following previous works	Whole road	Customer enquiries
Collier Street		Yalding	Maidstone	Road	Surface preservation	From "Lupofresh" to Jarmons Lane	Condition survey
Coombe Road		Tovil	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Dane Court		Coxheath	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Detling Hill/ Sittingbourne Road	A249	Detling / Thurnham / Stockbury	Maidstone	Crash barriers	Upgrade tensioned corrugated beam (TCB) safety fencing	Various sections between County Show Ground and Church Hill, Stockbury	Condition survey
Egremont Road		Bearsted	Maidstone	Footway	Footway preservation	Entire length	Identified by survey
Eynhorne Street		Hollingbourne	Maidstone	Drainage	Install additional drainage on Hollingbourne Hill	Near the Church and Upper Street, at junction with Pilgrims Way	Risk assessment
Fairmeadow	A229	Maidstone	Maidstone	Traffic Signals	Signal junction refurbishment	At the junction with Medway Street	Annual review of equipment age, specification and fault rate
Faversham Road		Lenham	Maidstone	Road	Surface preservation	A20 to Old Lenham Road	Local needs
Forstal Road		Aylesford	Maidstone	Road	Road renewal	From bridge deck over motorway to Beddow Way	Local needs
Freeman Way		Maidstone	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Gallants Lane		East Farleigh	Maidstone	Road	Surface preservation	From Lower Road to Heath Road	Condition survey
Garden Close		Maidstone	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Gatland Lane		Maidstone	Maidstone	Road	Surface preservation	From Farleigh Lane to Fant Lane	Post A26 collapse – preservation works
Glebe Lane		Maidstone	Maidstone	Road	Surface preservation	From Tonbridge Road to Farleigh Lane	Post A26 collapse – preservation works
Goudhurst Road		Cranbrook	Maidstone	Road	Surface preservation	From Curtisden Green Lane to Loves Farm	Condition survey
Gravelly Bottom Road		Lenham	Maidstone	Road	Surface preservation	From Lenham Road to Broomfield Road	Condition survey
Hart Street/Barker Road		Maidstone	Maidstone	Road	Surface preservation	From McDonald's to Clifford Way	Condition survey
Headcorn Road		Lenham	Maidstone	Road	Surface preservation	From Chain Gate Road to Station Approach, Lenham	Condition survey
Headcorn Road		Sandway	Maidstone	Road	Surface preservation	From Headcorn Road to Sandway Road	Condition survey
Heath Road		Coxheath	Maidstone	Road	Surface preservation	From Stockett Lane to Vanity Lane	Condition survey
Heath Road		Coxheath	Maidstone	Road	Surface preservation	From Woodlands to Ewell Lane	Condition survey
Hildenborough Crescent		Allington	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Hunton Road		Marden	Maidstone	Road	Surface preservation	From River Beult Bridge (Clapper Green) To 'Reed Court Cottages'	Condition survey

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Kenward Road		Yalding	Maidstone	Road	Surface preservation	From Hunt Street to Yalding Hill	Condition survey
King Street	A20	Maidstone	Maidstone	Road	Road renewal	Wat Tyler Way and Wyke Manor Road	Condition survey
Lenham Road		Kingswood	Maidstone	Road	Surface preservation	From Gravelly Bottom Road to Chegworth Lane	Condition survey
Linton Road	A229	Loose	Maidstone	Road	Road renewal	From Lancet Lane to Rosemount Close	Local needs
London Road (Rocky Hill)	A20/A26	Maidstone	Maidstone	Road	Road renewal	Maidstone gyratory to Terrace Road	Resilient Highway Network
Loose Road		Loose	Maidstone	Footway	Footway renewal	North side only between Loose Primary School and Barcham Court	Identified by survey
Loose Road	A229	Loose	Maidstone	Road	Road renewal	Between Wheatsheaf Pub and Cripple Street	Condition survey
Maidstone Road		Marden	Maidstone	Road	Surface preservation	From 'Hartridge' to 150 metres north of junction with Milebush Lane (Kiln Farm)	Condition survey
Maidstone Road	A274	Sutton Valence	Maidstone	Road	Road renewal	From the B2163 Upper Street to Warmlake Road	Road grip survey
Maidstone Road		Nettlestead	Maidstone	Road	Surface preservation	From Wheelbarrow roundabout (East Peckham Bypass) to Bow Road	Condition survey
Marden Road		Staplehurst	Maidstone	Road	Surface preservation	From Battle Lane to 'Mountain Farmhouse'	Condition survey
Marden Road		Staplehurst	Maidstone	Road	Surface preservation	From Maxted Close to 150 metres west of junction with Clapper Lane	Condition survey
Marion Crescent			Maidstone	Soft Landscape	Tree scheme	Various locations	Tree improvement scheme

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Mill Street	A20	Maidstone	Maidstone	Structures	Structural painting	Parapets to Mill Street bridge (KCC Structure No. 3698)	Condition survey
Oad Street		Stockbury	Maidstone	Road	Surface preservation	Between A249 and Pett Lane	Condition survey
Old Ham Lane		Sandway	Maidstone	Road	Road reconstruction (recycling)	From Railway Bridge to Ham Lane	Condition survey
Old Tree Lane/Cliff Hill		Boughton Monchelsea	Maidstone	Road	Surface preservation	From 'The Quarries' to Combe Bank House -	Condition survey
Pagehurst Road		Staplehurst	Maidstone	Road	Road reconstruction (recycling)	From Marden Road to Thorn Road	Local needs
Palace Avenue	A229	Maidstone	Maidstone	Road	Road renewal	Extents to be determined	Condition survey
Palace Avenue	A229	Maidstone	Maidstone	Road	Road renewal	Between Mill Street and A249 Mote Road	Condition survey
Pattenden Lane		Marden	Maidstone	Drainage	Full survey to be undertaken and scheme developed	Under railway bridge	Customer enquiries
Rocky Hill	A20/A26	Maidstone	Maidstone	Road	Road renewal	From Maidstone gyratory to Terrace Road	Resilient Highway Network
Romney Close		Bearsted	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Roseholme		Fant	Maidstone	Footway	Footway preservation	Entire length	Identified by survey
Rosemary Road		Bearsted	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Royston Road		Bearsted	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Sandling Lane		Penenden Heath	Maidstone	Road	Surface preservation	From Boxley Road to the 40 mph speed limit gateway just past The Hedges	Condition survey
Sandway Road		Sandway	Maidstone	Road	Surface preservation	Around 'Sandway Triangle'	Condition survey
Sandway Road		Sandway	Maidstone	Road	Surface preservation	From Headcorn Road to 'Little Biggen'	Condition survey
Sheals Crescent		Maidstone	Maidstone	Drainage	Full survey to be undertaken and scheme developed	Whole road	Section 19 Flooding Identification

MAIDSTONE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Sheals Crescent	A229	Maidstone	Maidstone	Road	Road renewal	From Loose Road (Through Hayle Road, College Road, Mill Street) to Bishops Way	Local needs
Sheppey Road		Loose	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sheridan Close		Ringlestone	Maidstone	Road	Surface preservation	Dickens Road to No. 8	Condition survey
Sittingbourne Road	A249	Maidstone	Maidstone	Road	Road renewal	Andrew Broughton Way to Bearsted Road	Condition survey
Smiths Hill		West Farleigh	Maidstone	Road	Surface preservation	Hunt Street to Shingle Barn Lane	Condition survey
Southernden Road		Edgerton	Maidstone	Road	Road reconstruction (recycling)	From Grigg Lane to end	Condition survey
Spencer Way		Maidstone	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Staffa Road		Loose	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sussex Road		Shepway	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Tilden Lane		Headcorn	Maidstone	Road	Road reconstruction (recycling)	From Stilebridge Lane to Underlin Lane	Condition survey
Tonbridge Road	A26	Maidstone	Maidstone	Traffic Signals	Signal junction renewal	Junction with Fountain Lane	Annual review of equipment age, specification and fault rate

MAIDSTONE							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Tonbridge Road	A26	Maidstone	Maidstone	Traffic Signals	Signal crossing refurbishment	Near Milton Street	Annual review of equipment age, specification and fault rate
Trenton Close		Allington	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Tufa Close		Boxley	Maidstone	Drainage	Install new deep bore soakaway	Within turning circle	Risk assessment
Upper Stone Street	A229	Maidstone	Maidstone	Road	Road renewal	From A249 Mote Road to Old Tovil Road	Condition survey
Ware Street		Bearsted	Maidstone	Footway	Footway preservation	From Sandy Lane to White Horse public house	Identified by survey
Wesley Close		Barming	Maidstone	Footway	Footway preservation	Entire length	Identified by survey
West Street		Lenham	Maidstone	Road	Surface preservation	From Faversham Road to Flint Lane	Condition survey
Wheelers Lane		Linton	Maidstone	Road	Surface preservation	From Linton Hill to Vanity Lane	Condition survey
Willington Street		Maidstone	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Wilson Close		Maidstone	Maidstone	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Winifred Road		Bearsted	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Woodlands		Coxheath	Maidstone	Footway	Footway renewal	Entire length	Identified by survey
Woodside Green		Lenham and Doddington	Maidstone	Road	Surface preservation	From Old Lenham Road to material joint (by metal gate) towards Ringlestone Road (Doddington)	Condition survey

SEVENOAKS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Beesfield Lane		Farningham	Sevenoaks	Road	Surface preservation	From A225 to Donkey Lane	Condition survey
Betenson Avenue		Sevenoaks	Sevenoaks	Structures	Bridge strengthening	Betenson Bridge (KCC Structure No. 1445) carrying watercourse under road	Condition survey
Bitchett Green Road		Seal	Sevenoaks	Road	Surface preservation	From Carters Hill to Rooks Hill	Condition survey
Bradbourne Vale Road			Sevenoaks	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Buckhurst		Markbeech	Sevenoaks	Road	Surface preservation	From Uckfield Lane to Buckhurst Lane	Condition survey
Button Street		Swanley	Sevenoaks	Road	Surface preservation	From M25 overbridge to bridge over M20	Condition survey
Camp Hill			Sevenoaks	Road	Surface preservation	From B2027 to Compasses Road	Condition survey
Carters Hill		Underriver	Sevenoaks	Road	Surface preservation	From Underriver House Road to Bank Lane	Condition survey
Carters Hill		Underriver	Sevenoaks	Road	Surface preservation	From Underriver House Road to Fawke Road	Condition survey
Cleves Road		Kemsing	Sevenoaks	Footway	Footway preservation	Entire length	Identified by survey
Cockerhurst Road		Shoreham	Sevenoaks	Road	Surface preservation	From Shacklands Road to Redlands Lane	Condition survey
Cold Arbor Road		Sevenoaks	Sevenoaks	Road	Surface preservation	From A25 to overbridge to A21	Condition survey
Coppings Road		Leigh	Sevenoaks	Road	Surface preservation	From Compasses Road to Scabharbour Road	Condition survey
Cow Lane		Mark Beech	Sevenoaks	Road	Surface preservation	From Cowden Pound Road to Station Road	Condition survey
Crowhurst Lane		West Kingsdown	Sevenoaks	Road	Surface preservation	From Billet Hill to A20	Condition survey

SEVENOAKS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Four Elms Road	B2027	Edenbridge	Sevenoaks	Road	Surface preservation	From Swan Lane to Pootings Road	Local needs
Franks Lane		Horton Kirby	Sevenoaks	Road	Surface preservation	From A225 to Eglantine Lane	Condition survey
Glebe Road		Sevenoaks Weald	Sevenoaks	Road	Road reconstruction (recycling)	Hubbards Hill to Windmill Road	Condition survey
Gracious Lane		Sevenoaks	Sevenoaks	Road	Surface preservation	From Rycroft Lane to Wheatsheaf Hill	Condition survey
Grove Road		Sevenoaks	Sevenoaks	Road	Surface preservation	From B2188 to Finch Green	Condition survey
Hartfield Road	B2026	Cowden	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
Hartley Bottom Road		New Ash Green	Sevenoaks	Road	Surface preservation	From Manor Road to B260 Main Road	Condition survey
High Street		Cowden	Sevenoaks	Road	Surface preservation	High Street and Cowden Road, from District boundary (Kitford Bridge) to The Priors	Condition survey
High Street		Brasted	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
Ide Hill Road		Ide Hill	Sevenoaks	Road	Surface preservation	From Coopers Corner to Clinton Lane	Condition survey
Ide Hill Road		Edenbridge	Sevenoaks	Road	Surface preservation	From Four Elms to Toys Hill	Condition survey
Ide Hill Roundabout To Wheatsheaf Hill			Sevenoaks	Road	Surface preservation	From village roundabout to Wheatsheaf Hill	Condition survey
Leydenhatch Lane		Swanley	Sevenoaks	Road	Surface preservation	From Birchwood Road to New Barn Road	Condition survey
London Road		West Kingsdown	Sevenoaks	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
London Road	A20	Dunton Green	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
London Road	A233	Westerham	Sevenoaks	Road	Surface preservation	From Beggars Lane to Market Square	Local needs

SEVENOAKS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
London Road, Wrotham			Sevenoaks	Drainage	Drainage improvements	To be determined	Risk assessment
Main Road		Sundridge	Sevenoaks	Drainage	Full survey to be undertaken and scheme developed	Near to Village Hall	Customer enquiries
Main Road	B2026	Edenbridge	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
Main Road		Edenbridge	Sevenoaks	Road	Surface preservation	From Rushmore Hill to Pound Lane	Condition survey
Maplescombe Lane		Farningham	Sevenoaks	Road	Surface preservation	From Donkey Lane to Botsum Lane	Condition survey
Mapleton Road		Westerham	Sevenoaks	Road	Surface preservation	From Pootings Road to Puddledock Lane	Condition survey
Marsh Green Road		Edenbridge	Sevenoaks	Road	Surface preservation	From B2026 Mill Hill to the Marsh Green village gateway	Condition survey
Old Marsh Green Road		Edenbridge	Sevenoaks	Road	Surface preservation	From B2028 Marsh Green Road to B2028 Marsh Green Road	Protection following recycling (retread)
Orpington Bypass Road			Sevenoaks	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Park Lane		Kemsing	Sevenoaks	Footway	Footway preservation	Entire length	Identified by survey
Pease Hill		Ash	Sevenoaks	Road	Surface preservation	From South Ash Road to Hartley Bottom Road	Condition survey
Pilgrims Way		Kemsing	Sevenoaks	Road	Surface preservation	From Childsbridge Lane to The Landway	Condition survey
Pilgrims Way		Westerham	Sevenoaks	Road	Surface preservation	From Westerham Hill to Croydon Road	Condition survey
Polhill		Halstead	Sevenoaks	Road	Road renewal	From Otford Road to change of surfacing	Local needs

SEVENOAKS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Pootings Road	B269	Westerham	Sevenoaks	Structures	Bridge reconstruction	Pootings 1 (KCC Structure No. 2133) carrying watercourse under road	Condition survey
Poundsbridge Hill		Penshurst	Sevenoaks	Road	Surface preservation	From Poundsbridge to The Lane	Condition survey
Poundsbridge Lane		Penshurst	Sevenoaks	Road	Surface preservation	From B2176 Penshurst Road to Poundsbridge	Condition survey
Powder Mill Lane		Leigh	Sevenoaks	Road	Surface preservation	From 30 mph/national speed limit signs to 50 metres past The Plough Inn	Condition survey
Row Dow		Otford	Sevenoaks	Road	Surface preservation	From Pilgrims Way East to Birching Cross	Condition survey
Rushymead		Kemsing	Sevenoaks	Footway	Footway preservation	Entire length	Identified by survey
Sevenoaks Road		Otford	Sevenoaks	Footway	Footway renewal	Entire length	Identified by survey
Shoreham Road		Eynsford	Sevenoaks	Road	Surface preservation	From Castle Road to Preston railway bridge	Condition survey
Station Road		Halstead	Sevenoaks	Road	Surface preservation	From Clarks Lane to Cadlocks Hill	Condition survey
Station Road		Edenbridge	Sevenoaks	Road	Road renewal	From Wellingtonia Way to High Street	Local needs
Stone Street		Seal	Sevenoaks	Road	Surface preservation	From Blakes Green Road to District boundary	Condition survey
Sundridge Road		Chevening	Sevenoaks	Road	Surface preservation	From Polhill Roundabout to crossroads at Chevening Road	Condition survey
Swanley Lane	B258	Swanley	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
Swanley Village Road		Swanley	Sevenoaks	Road	Surface preservation	From Beechenlea Road to Button Street	Condition survey
Tonbridge Road	B2027	Sevenoaks	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey

SEVENOAKS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Tonbridge Road		Leigh	Sevenoaks	Road	Surface preservation	From Penshurst Road to Compasses Road	Condition survey
Top Dartford Road	B258	Hextable	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
Twitton Lane		Otford	Sevenoaks	Road	Surface preservation	From Pilgrims Way West to Filston Lane	Condition survey
Valley Road		Fawkham	Sevenoaks	Road	Surface preservation	From Sun Hill to Scudders Hill	Condition survey
Watery Lane		Kemsing	Sevenoaks	Road	Surface preservation	Industrial estate to Heaverham Road	Condition survey
Watery Lane		Kemsing	Sevenoaks	Road	Surface preservation	From Saxbys to A25	Condition survey
Westerham Road	A25	Westerham	Sevenoaks	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Wood Street		Swanley	Sevenoaks	Road	Surface preservation	From Button Street to village gateway	Condition survey
High Street	A225	Brasted	Sevenoaks	Road	Road renewal	Extents to be determined	Condition survey
London Road	B2173	Swanley	Sevenoaks	Road	Road renewal	From M20 overbridge to Goldsel Road roundabout	Road grip survey
Main Road	B2026	Crockham Hill	Sevenoaks	Road	Road renewal	From Hosey Common Road to Spout Lane	Condition survey
Sevenoaks Road	A225	Otford	Sevenoaks	Road	Road renewal	From M26 overbridge to Vestry Road	Condition survey
Sevenoaks Road	A225	Otford	Sevenoaks	Road	Road renewal	Southbound carriageway, junction with Vestry Road	Condition survey

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Allenby Walk		Sittingbourne	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Ambleside		Sittingbourne	Swale	Footway	Footway preservation	Entire length	Identified by survey
Bagshill Road		Leaveland/ Throwley	Swale	Road	Surface preservation	From A251 to Parsonage Stocks Road	Condition survey
Bank Street		Faversham	Swale	Road	Road renewal	From junction with Stone Street to car park	Local needs
Barton Hill Road		Minster on Sea	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Beaconsfield Road		Sittingbourne	Swale	Footway	Footway renewal	Entire length	Identified by survey
Bell Road		Sittingbourne	Swale	Soft Landscape	Tree scheme	Various locations	Tree improvement scheme
Bell Road	B2163		Swale	Traffic Signals	Signal junction renewal	Junction with Avenue Of Remembrance	Annual review of equipment age, specification and fault rate
Blenheim Road		Sittingbourne	Swale	Footway	Footway renewal	Entire length	Identified by survey
Bridge Road	A250	Sheerness	Swale	Road	Road renewal	North of High Street junction	Local needs
Broom Road		Sittingbourne	Swale	Footway	Footway renewal	Exact extents to be determined	Identified by survey
Bysing Wood Road		Luddenham	Swale	Road	Surface preservation	From edge of surface dressing to Tin Shop Hill	Condition survey
Canterbury Road	A2	Snipeshill	Swale	Drainage	Full survey to be undertaken and scheme developed	Open space at Greenways	2018 flood event and customer enquiries

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Christophers Row		Lynsted with Kingsdown/ Doddington	Swale	Road	Surface preservation	From national speed limit sign (Lynsted) to motorway bridge	Condition survey
Church Hill		Hernhill	Swale	Road	Surface preservation	From Kemsdale Road to Staple Street	Condition survey
Coats Avenue		Sheerness	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Cold Harbour Lane including Bobbing Hill		Bobbing	Swale	Road	Surface preservation	From Rook Lane to Keycol Roundabout	Condition survey
Collingwood Walk		Sittingbourne	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Dorset Road		Sheerness	Swale	Footway	Footway renewal	Entire length	Identified by survey
Down Court Road		Doddington	Swale	Road	Surface preservation	From Chequers Hill to Sawpit	Condition survey
Dully Road		Tonge	Swale	Road	Surface preservation	From A2 to Upper Road	Condition survey
Eagles Close		Sittingbourne	Swale	Footway	Footway renewal	Exact extents to be determined.	Identified by survey
Eastchurch Road		Eastchurch	Swale	Road	Surface preservation	From roundabout to A2500 Lower Road	Condition survey
Eastling Road		Eastling	Swale	Road	Surface preservation	From Kettle Hill Road To Evelyn Road	Condition survey
Eastling Road		Eastling	Swale	Road	Surface preservation	From Plumford Lane to Scotts Lane	Condition survey
Featherbed Lane (South Street/Foxes Lane)		Selling	Swale	Road	Surface preservation	From Selling Road to Scaggers Hill	Condition survey

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Frinsted Road		Milstead	Swale	Road	Surface preservation	From Horn Hill to Torry Hill Road	Condition survey
Head Hill		Graveney with Goodnestone	Swale	Road	Surface preservation	From A2 to Sandbanks Road	Condition survey
Hickmans Green (Horseless Road)		Boughton Under Blean/Dunkirk	Swale	Road	Surface preservation	From Snake Lane to Thunderhill Business Park	Condition survey
High Street	A2	Eastchurch	Swale	Road	Road renewal	From Bus layby to Church Lane	Condition survey
High Street	A250	Eastchurch	Swale	Road	Road renewal	From Millennium Way to Victoria Street	Local needs
High Street		Sittingbourne	Swale	Road	Road renewal	Full length of Sittingbourne High Street and Central Avenue	Local needs
Lansdown Road		Sittingbourne	Swale	Footway	Footway renewal	From Gladstone Drive to Peel Drive	Identified by survey
Linden Drive		Sheerness	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
London Road		Sittingbourne	Swale	Drainage	Full survey to be undertaken and scheme developed	Various locations	Customer enquiries
London Road	A2	Faversham	Swale	Road	Road renewal	From Church Lane to Bull Lane	Condition survey
London Road	A2	Faversham	Swale	Road	Surface preservation	From Hempstead Lane to East Street (except new estate section)	Condition survey
London Road	A2	Faversham	Swale	Road	Surface preservation	From Love Lane to Western Link	Condition survey

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
London Road	A2	Faversham	Swale	Road	Road renewal	From The Billet public house for a distance of 100 metres east towards Sittingbourne town centre / between Adelaide Drive and Lydbrook Close	Local needs
Lower Hartlip Road		Hartlip/ Stockbury	Swale	Road	Surface preservation	From A2 to Yelstead	Condition survey
Lower Road	A2500	Eastchurch	Swale	Road	Road renewal	Extents to be determined	Condition survey
Lower Road		Teynham	Swale	Road	Surface preservation	From Frognal Lane to Station Road	Condition survey
Lower Road/ Bysingwood Road		Faversham	Swale	Road	Surface preservation	From property 'Bennetts Gardens' to Tin Shop Lane	Condition survey
Luddenham Road		Luddenham	Swale	Road	Surface preservation	From Luddenham Church Road to Luddenham	Condition survey
Main Road	B2007	Queenborough	Swale	Structures	Structural painting	Access ramp parapets to Queenborough Station Footbridge (KCC Structure No. 1101)	Condition survey
Menin Road		Kemsley	Swale	Footway	Footway preservation	From The Square to Ypres Drive	Identified by survey
Millennium Way	A250	Sheerness	Swale	Road	Road renewal	50 metres on each approach to High Street	Local needs
Millennium Way	A250	Sheerness	Swale	Road	Road renewal	50 metres on each approach to High Street	Local needs
Minster Road		Minster on Sea	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Minster Road	B2008		Swale	Traffic Signals	Signal crossing renewal	Near Lowfield Road	Annual review of equipment age, specification and fault rate
Nelson Walk		Sittingbourne	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
New Road		Sheerness	Swale	Footway	Footway renewal	Various sections throughout entire length	Identified by survey
New Road		Sheppey	Swale	Soft Landscape	Tree scheme	Various locations	Tree improvement scheme
Oak Road		Sittingbourne	Swale	Footway	Footway renewal	From Tonge Road To Great East Hall Road.	Identified by survey
Ospringle Street - London Road		Faversham	Swale	Drainage	Full survey to be undertaken and scheme developed	Near the junction with Water Lane	Customer enquiries
Parsonage Stocks Road		Throwley	Swale	Road	Surface preservation	From Bagshill Road to Old Badgins Road	Condition survey
Petts Dane Road		Eastling	Swale	Road	Surface preservation	Whole length from Kettle Hill Road to Stalisfield	Condition survey
Queensway		Sheerness	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
River View		Queenborough	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Rosemary Avenue		Sheerness	Swale	Footway	Footway preservation	Entire length	Identified by survey
St Michaels Road	A2	Sittingbourne	Swale	Road	Road renewal	From Forum to Crown Quay Lane	Local needs

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
St Michaels Road	A2	Sittingbourne	Swale	Road	Road renewal	Extents to be determined	Condition survey
Stalisfield Road		Ospringe	Swale	Road	Surface preservation	From Sooks Hill to Throwley Road	Condition survey
Staplehurst Road		Sittingbourne	Swale	Structures	Structural painting	Staplehurst Road Footbridge South (KCC Structure No. 3091)	Condition survey
Summerville Avenue		Minster on Sea	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sunnyfields Drive		Queenborough	Swale	Footway	Footway preservation	Entire length	Identified by survey
Thanet Way	A299	Graveney with Goodnestone / Hernhill	Swale	Crash barriers	Upgrade tensioned corrugated beam (TCB) safety fencing	Staple Street to Wey Street	Condition survey
Thanet Way	A299	Hernhill	Swale	Road	Road renewal	Extents to be determined	Condition survey
The Broadway		Sheppey	Swale	Soft Landscape	Tree scheme	Various locations	Tree improvement scheme
The Street		Hartlip	Swale	Road	Surface preservation	From Dane Lane to Place Lane	Condition survey
The Street	A2		Swale	Traffic Signals	Signal crossing renewal	Near School Lane	Annual review of equipment age, specification and fault rate
The Willows		Newington	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Tonge Corner Road		Tonge	Swale	Drainage	Full survey to be undertaken and scheme developed	Tonge Corner	Customer enquiries

SWALE

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Tonge Road and Lomas Road		Sittingbourne	Swale	Road	Surface preservation	From Church Road (Sittingbourne) To Church Road (Tonge)	Condition survey
Tunstall Road		Sittingbourne	Swale	Drainage	re-shape driveway and cleanse drainage system	Whole road	Risk assessment
Wellington Road		Sittingbourne	Swale	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Whitstable Road	B2040	Faversham	Swale	Road	Road renewal	Extents to be determined	Condition survey
Wrens Road		Borden/ Bredgar	Swale	Road	Surface preservation	From Sutton Baron Road to M2 bridge	Condition survey

THANET							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Addiscombe Road		Margate	Thanet	Road	Surface preservation	From Rosedale Road to Dane Road	Condition survey
Alfred Road		Birchington	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Allenby Road		Ramsgate	Thanet	Road	Road renewal	From Margate Road to Newington Road	Local needs
Bradley Road		Ramsgate	Thanet	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Broadstairs Road	A255	Broadstairs	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Callis Court Road		Broadstairs	Thanet	Road	Surface preservation	From railway bridge to Reading Street	Condition survey
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	From Marine Terrace roundabout to B2051 Marine Drive	Resilient Highway Network
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	From Minster Road to Bridge Road	Resilient Highway Network
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	From Old Crossing Road to Marine Terrace roundabout	Resilient Highway Network
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	From Park Road to Minster Road	Resilient Highway Network
Canterbury Road	A28	Birchington	Thanet	Road	Road renewal	From Seamark Road to Kent Gardens	Resilient Highway Network
Canterbury Road East	A299	Ramsgate	Thanet	Soft Landscape	Tree planting scheme	Roundabout to Shell garage - various locations	Tree improvement scheme
Canterbury Road West	A299	Ramsgate	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Canterbury Road West	A299	Ramsgate	Thanet	Road	Road renewal	From Hengist Way to Haine Road	Condition survey

THANET

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Cliff Terrace		Margate	Thanet	Road	Surface preservation	From Sion Place to Athesden Road	Condition survey
College Road	B2052	Margate	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Convent Road / George Hill Road		Broadstairs and St. Peters	Thanet	Road	Surface preservation	From Percy Avenue to Reading Street Road	Condition survey
Dane Court Road		Broadstairs	Thanet	Drainage	Full survey to be undertaken and scheme developed	Roundabout and on to A256	Customer enquiries
Dumpton Park Drive		Broadstairs	Thanet	Road	Surface preservation	From Dumpton Gap Road to Merriville Heights	Condition survey
Eaton Road	A254	Margate	Thanet	Road	Road renewal	50 metres on the approach to A254/A255 roundabout including circulatory of roundabout	Local needs
Ethelbert Road		Birchington	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Fairfield Road		Broadstairs	Thanet	Road	Road renewal	Extents to be determined	Local needs
Gloucester Avenue (North)		Margate	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Green Lane		Margate	Thanet	Road	Surface preservation	From Northdown Park Road to Victoria Avenue	Local needs
Haine Road	A256	Ramsgate	Thanet	Road	Road renewal	Around West Cross	Condition survey
Harold Road		Birchington	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Hilda Road		Minster	Thanet	Drainage	Review of any outstanding issues following previous works	Whole road	Customer enquiries
Manor Road		St Nicholas at Wade	Thanet	Road	Surface preservation	From Canterbury Road to School House	Condition survey

THANET							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Manston Court Road		Margate	Thanet	Road	Surface preservation	From Star Lane Link to Manston Road	Local needs
Manston Road		Birchington	Thanet	Road	Surface preservation	From Shottenden Road to waste recycling tip	Condition survey
Margate Road	A254	Ramsgate	Thanet	Soft Landscape	Tree planting scheme	Homeleigh Road to Pysons Road - various locations	Tree improvement scheme
Millmead / College Road	B2050	Margate	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Millmead Road	B2052	Margate	Thanet	Road	Road renewal	Extents to be determined	Condition survey
Nash Road		Margate	Thanet	Road	Surface preservation	From Shottendane Road to Star Lane Link	Local needs
Netherhale Farm Road		St. Nicholas at Wade	Thanet	Road	Surface preservation	From the junction with Canterbury Road	Condition survey
Northdown Park Road		Margate	Thanet	Road	Surface preservation	From Upper Dane Road to Approach Road	Condition survey
Northdown Road		Margate	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Palm Bay Avenue		Margate	Thanet	Road	Surface preservation	From medical centre to Bay View	Condition survey
Park Lane		Birchington	Thanet	Road	Surface preservation	From Kings Road to Manston Road	Condition survey
Princes Gardens		Margate	Thanet	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Princess Margaret Avenue		Margate	Thanet	Road	Surface preservation	Extents to be determined	Condition survey
Princess Margaret Avenue		Margate	Thanet	Road	Surface preservation	From Eastchurch Road to junction with B2051	Condition survey
Ramsgate Road	A255	Birchington	Thanet	Road	Road renewal	From East Kent College to Park Avenue	Condition survey

THANET							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ramsgate Road	A255		Thanet	Traffic Signals	Signal crossing renewal	Dumpton Bypass	Annual review of equipment age, specification and fault rate
Rancorn Road		Margate	Thanet	Road	Surface preservation	From Westbrook Avenue to Westbrook Gardens	Condition survey
Saltwood Gardens		Margate	Thanet	Footway	Footway renewal	Entire length	Identified by survey
Sandwich Road		Ramsgate	Thanet	Road	Surface preservation	From Cliffs End Road to A299	Condition survey
Sandwich Road		Cliffs End	Thanet	Road	Surface preservation	From Foads Lane to Cliffs End Road	Condition survey
South Eastern Road		Ramsgate	Thanet	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
Sowell Street		Broadstairs	Thanet	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Spitfire Way	B2190	Minster	Thanet	Road	Road renewal	Extents to be determined	Condition survey
St Mildreds Road		Westgate On Sea	Thanet	Road	Surface preservation	From Station Road to Harold Avenue	Condition survey
St Peters Road		Broadstairs	Thanet	Road	Surface preservation	From Harrow Dene to Crawford Road	Condition survey
St. Peters Road		Margate	Thanet	Drainage	Full survey to be undertaken and scheme developed	Linked to Dane Court Road	Customer enquiries
Stone Road		Broadstairs	Thanet	Road	Surface preservation	From Lanthorn Road to North Foreland Avenue	Condition survey

THANET							
Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Thanet Way	A299	Birchington / St Nicholas At Wade	Thanet	Crash barriers	Upgrade tensioned corrugated beam (TCB) safety fencing	Various sections between Thanet DC boundary and St. Nicholas at Wade roundabout (works continue into Canterbury CC area)	Condition survey
Thanet Way	A299	St Nicholas at Wade	Thanet	Structures	Culvert strengthening	Wantsum culvert (KCC Structure No. 275) carrying River Wantsum under road (also listed under Canterbury District)	Condition survey
Thanet Way	A299	St Nicholas at Wade	Thanet	Structures	Preventative maintenance to corrugated steel culvert	Wade Marsh Stream Culvert (KCC Structure No. 277) carrying watercourse under road	Condition survey
Upper Hale		St. Nicholas at Wade	Thanet	Road	Surface preservation	From the junction with Canterbury Road	Condition survey
Upton Road		Broadstairs	Thanet	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Wayborough Hill		Minster	Thanet	Drainage	Install two new 2.4 metre x 5.5 metre soakaways with four new gullies	At the junction of Wayborough Hill with Way Hill and outside Primrose Cottage	Risk assessment
Westbrook Avenue		Margate	Thanet	Road	Surface preservation	From Barnes Avenue to Rancorn Road	Condition survey
Whitehall Road		Ramsgate	Thanet	Road	Surface preservation	From A254 Margate Road to Hurst Green	Condition survey

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ashes Lane		Hadlow	Tonbridge & Malling	Road	Surface preservation	From A26 Hadlow Road to High House Lane	Condition survey
Ashton Way (Roundabout)	A228	West Malling	Tonbridge & Malling	Road	Road renewal	Extent of roundabout and approaches (King Hill/Ashton Way)	Local needs
Borough Green Road		Borough Green	Tonbridge & Malling	Road	Surface preservation	From Kemsing Road to A227 Wrotham by-pass	Condition survey
Broadoak		Leybourne	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Bull Lane		Aylesford	Tonbridge & Malling	Road	Surface preservation	From telephone exchange to Rowe Place Farm	Condition survey
Bull Lane / High Street		Wrotham	Tonbridge & Malling	Road	Surface preservation	From White Hill roundabout to High Street	Condition survey
Cannon Lane	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From A227 Hadlow Road East to B2017 Tudeley Lane	Condition survey
Castle Street		Tonbridge	Tonbridge & Malling	Road	Surface preservation	Whole length	Condition survey
Castle Way	A228	Leybourne	Tonbridge & Malling	Road	Road renewal	Between Leybourne Way and M20 Junction 4	Local needs
Church Walk & New Road		West Malling	Tonbridge & Malling	Drainage	Full survey to be undertaken and scheme developed	Whole road	Customer enquiries
Common Road		Ightham	Tonbridge & Malling	Road	Surface preservation	From A25 to A227	Condition survey
Comp Lane		Offham	Tonbridge & Malling	Road	Surface preservation	From Teston Road to Seven Mile Lane	Condition survey
East Peckham By-pass (Hale Street Bypass /	A228	East Peckham	Tonbridge & Malling	Road	Road renewal	From Hale Street roundabout To Hop Farm roundabout	Local needs

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Branbridges Road)							
Evergreen Close		Leybourne	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Fernbank Close		Walderslade	Tonbridge & Malling	Road	Surface preservation	Whole length	Condition survey
Forest Grove		Tonbridge	Tonbridge & Malling	Road	Surface preservation	From A227 Shipbourne Road to end	Condition survey
Hadlow Road		Tonbridge	Tonbridge & Malling	Road	Road renewal	Whole length	Local needs
Hadlow Road East		Tonbridge	Tonbridge & Malling	Road	Surface preservation	From A26 Hadlow Road to Three Elm Lane	Condition survey
Hadlow Road East	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From Three Elms to Cuckoo Lane	Condition survey
Half Moon Lane		Hildenborough	Tonbridge & Malling	Drainage	Install new drainage system including soakaway	Near the junction with Tonbridge Road	Risk assessment
Hall Road		Aylesford	Tonbridge & Malling	Drainage	Full survey to be undertaken and scheme developed	At the junction with the pumping station	Customer enquiries
Ham Hill Roundabout	A228	Snodland, Larkfield	Tonbridge & Malling	Road	Road renewal	Roundabout circulation area and both approaches	Remedial works
Hamptons Road		Shipbourne	Tonbridge & Malling	Road	Surface preservation	From the stream to Park Road	Condition survey
Harvest Ridge		Leybourne	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Henham Gardens		East Peckham	Tonbridge & Malling	Footway	Footway preservation	Entire length	Identified by survey
Heron Road		Larkfield	Tonbridge & Malling	Road	Surface preservation	Whole length	Condition survey
High Street		Wrotham	Tonbridge & Malling	Footway	Footway renewal	Entire length	Identified by survey
Judd Road		Tonbridge	Tonbridge & Malling	Road	Surface preservation	Whole length	Condition survey
Legge Lane		Birling	Tonbridge & Malling	Road	Surface preservation	Whole length to end	Condition survey
Leybourne Bypass	A228	Birling/Leybourne	Tonbridge & Malling	Road	Road renewal	Extents to be determined	Condition survey
Leybourne Way	C482	Larkfield	Tonbridge & Malling	Road	Road renewal	A228 to New Hythe Lane	Local needs
London Road	A20	East Malling	Tonbridge & Malling	Road	Road renewal	Castle Way to New Hythe Lane	Local needs
London Road	A20	West Malling	Tonbridge & Malling	Road	Road renewal	Extents to be determined	Condition survey
Long Mill Lane		Platt	Tonbridge & Malling	Road	Surface preservation	From Comp Lane to The Hurst	Condition survey
Lucks Hill		West Malling	Tonbridge & Malling	Drainage	Work with school for design feasibility	Near More Park RC Primary School	Risk assessment
Lunsford Lane		Larkfield	Tonbridge & Malling	Drainage	Surveys to be completed	North of M20 bridge	Risk assessment
Lunsford Lane		Larkfield	Tonbridge & Malling	Road	Surface preservation	From Leybourne Way to Great Lunsford Farm	Condition survey
Maidstone Road	A26	Hadlow	Tonbridge & Malling	Road	Surface preservation	From A228 roundabout to Hadlow	Condition survey
Maidstone Road	A26	Hadlow	Tonbridge & Malling	Road	Surface preservation	From A228 roundabout to start of 2017 resurfacing	Condition survey

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Maidstone Road	A26	Hadlow	Tonbridge & Malling	Road	Surface preservation	From Harrow Lane to start of surface dressing scheme	Condition survey
Malling Road	A228	Mereworth	Tonbridge & Malling	Road	Road renewal	Between A26 roundabout and Ashton Way roundabout	Condition survey
Mill Crescent		Tonbridge	Tonbridge & Malling	Structures	Deck Replacement	Mill Cottage Bridge (KCC Structure No. 3125) carrying mill race over access	Condition survey
Old Barn Road		Leybourne	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Old Church Road		East Peckham	Tonbridge & Malling	Road	Road reconstruction (recycling)	From A228 to A228 (whole crescent)	Condition survey
Old Road		East Peckham	Tonbridge & Malling	Road	Surface preservation	From Branbridges Lane to Snoll Hatch Lane	Condition survey
Park Road		West Peckham	Tonbridge & Malling	Road	Surface preservation	From Hamptons Road to Pillar Box Lane	Condition survey
Pembury Road	A2014		Tonbridge & Malling	Traffic Signals	Signal crossing renewal	Near St Marys Road	Annual review of equipment age, specification and fault rate
Pilgrims Way		Aylesford	Tonbridge & Malling	Road	Surface preservation	From High Street / Bull Lane to end	Condition survey
Plough Hill		Plaxtol	Tonbridge & Malling	Road	Surface preservation	From Crowhurst Lane to Claygate Cross	Condition survey
Plover Road		Larkfield	Tonbridge & Malling	Road	Surface preservation	From Swallow Road to Plover Road	Condition survey
Quarry Hill Road	A26	Tonbridge	Tonbridge & Malling	Road	Road renewal	Between Brook Street roundabout and A2014 Pembury Road roundabout	Local needs

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Quarry Hill Road	A26	Tonbridge	Tonbridge & Malling	Traffic Signals	Signal crossing renewal	Near St Stephen's Church	Annual review of equipment age, specification and fault rate
Robin Hood Lane		Walderslade	Tonbridge & Malling	Road	Surface preservation	From Taddington Wood Lane to Fostington Lane	Condition survey
Snodland Road		Snodland/ Birling	Tonbridge & Malling	Road	Surface preservation	From Hollow Lane to Legge Lane	Condition survey
Snoll Hatch Road		East Peckham	Tonbridge & Malling	Road	Surface preservation	From Hatches Lane to Old Road	Condition survey
Stacey Road		Tonbridge	Tonbridge & Malling	Footway	Footway preservation	Entire length	Identified by survey
Stair Road		Tonbridge	Tonbridge & Malling	Structures	Bridge strengthening	Stair Bridge (KCC Structure No. 212) carrying watercourse under road	Condition survey
Station Road		Aylesford	Tonbridge & Malling	Road	Surface preservation	Whole length from M20 overbridge to A20	Local needs
Stocks Green Road		Hildenborough	Tonbridge & Malling	Road	Surface preservation	From Leigh Road to 30 mph signs	Condition survey
Strawberry Vale		Tonbridge	Tonbridge & Malling	Structures	Deck replacement	Botany Footbridge (KCC Structure No. 3460) carrying pedestrians over Botany Stream	Condition survey
The Hurst		Plaxtol	Tonbridge & Malling	Road	Surface preservation	From footpath MR309 to junction with Long Mill Lane	Condition survey
The Hurst		Plaxtol	Tonbridge & Malling	Road	Surface preservation	From Swanton Valley to Adams Well Farm	Condition survey
The Ridgeway		Tonbridge	Tonbridge & Malling	Road	Road renewal	Pedestrian Crossing near the junction of Town Acres and	Local needs

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
						Junction with A26 Hadlow Road	
The Street		Plaxtol	Tonbridge & Malling	Road	Surface preservation	From School Lane to Dux Hill (including Long Mill Lane)	Condition survey
Three Elm Lane		Hadlow, Tonbridge	Tonbridge & Malling	Road	Surface preservation	From Tonbridge Road to A26	Local needs
Tonbridge Road	A26	Tonbridge	Tonbridge & Malling	Road	Road renewal	Extents to be determined	Condition survey
Tonbridge Road	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From Blackmans Lane to Hadlow	Condition survey
Tonbridge Road	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From Danns Lane to A228	Condition survey
Trottscliffe Road		Addington	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Tunbury Avenue		Walderslade	Tonbridge & Malling	Road	Road renewal	From Robin Hood Lane to Medway boundary	Remedial works
Vale Rise	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From A227 Hadlow Road East to B2017 Tudeley Lane	Condition survey
Vigo Road		Stanstead	Tonbridge & Malling	Road	Surface preservation	From Fairseat Lane to A227 Gravesend Road	Condition survey
Vines Lane		Hildenborough	Tonbridge & Malling	Road	Surface preservation	Whole length (Mill Lane to Riding Lane)	Condition survey
Western Road		Borough Green	Tonbridge & Malling	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
White Hill		Wrotham	Tonbridge & Malling	Road	Surface preservation	Whole length to end	Condition survey
Whitebine Gardens		East Peckham	Tonbridge & Malling	Footway	Footway preservation	Entire length	Identified by survey

TONBRIDGE & MALLING

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Woodgate Way	A26	Tonbridge	Tonbridge & Malling	Road	Surface preservation	From A227 Hadlow Road East to B2017 Tudeley Lane	Condition survey
Yardley Park Road		Tonbridge	Tonbridge & Malling	Road	Surface preservation	Whole length	Local needs

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Ashurst Bridge	A264		Tunbridge Wells	Traffic Signals	Signal junction renewal	Ashurst Road	Annual review of equipment age, specification and fault rate
Barden Road		Bidborough	Tunbridge Wells	Road	Surface preservation	From Penshurst Hill to 50 metres past Furze-fields	Condition survey
Barretts Road		Hawkhurst	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Bayham Road		Tunbridge Wells	Tunbridge Wells	Road	Surface preservation	From East Sussex boundary (east end of Tunbridge Wells crematorium) to Forest Road	Condition survey
Bidborough Ridge		Bidborough	Tunbridge Wells	Road	Surface preservation	From A21 to Mill Court	Condition survey
Blackhurst Lane		Tunbridge Wells	Tunbridge Wells	Road	Surface preservation	Between Sandown Park and 'no through road' end	Condition survey
Bodiam Road		Sandhurst	Tunbridge Wells	Road	Surface preservation	From A268 Queen Street, Sandhurst to East Sussex boundary ('The Mill House')	Condition survey
Brenchley Road		Brenchley	Tunbridge Wells	Road	Surface preservation	From 50 metres west of Petteridge Lane ('Myrtle Cottage') to Crook Road (opposite Brenchley Memorial Hall)	Condition survey
Brick Kiln Lane		Horsmonden	Tunbridge Wells	Road	Road reconstruction (recycling)	From Rectory Park Road to Spelmonden Road	Condition survey
Broomhill Road		Rusthall	Tunbridge Wells	Road	Surface preservation	From Speldhurst Road to Lower Green Road	Condition survey

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Burslem Road		Tunbridge Wells	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Calverley Road	A264	Tunbridge Wells	Tunbridge Wells	Traffic Signals	Signal junction renewal	Junction with Camden Road	Annual review of equipment age, specification and fault rate
Clayhill Road		Lamberhurst	Tunbridge Wells	Road	Surface preservation	From B2169 Furnace Lane to A21 Lamberhurst Quarter	Condition survey
College Drive		Tunbridge Wells	Tunbridge Wells	Footway	Footway preservation	Entire length	Identified by survey
Colliers Green Road		Cranbrook	Tunbridge Wells	Road	Surface preservation	From A262 to Colliers Green School	Condition survey
Colts Hill	A228	Capel	Tunbridge Wells	Road	Surface preservation	From Alders Road to Maidstone Road (Pembury)	Local needs
Concord Close		Tunbridge Wells	Tunbridge Wells	Footway	Footway preservation	Entire length	Identified by survey
Constitutional Hill Road and Church Road		Southborough	Tunbridge Wells	Road	Surface preservation	Including Church Road from A26 to Holden Pond	Condition survey
Cranbrook Road		Hawkhurst	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Crittenden Road and Chestnut Lane		Matfield	Tunbridge Wells	Road	Surface preservation	From A228 Colts Hill to Maidstone Road, Matfield	Condition survey
Cromwell Road		Tunbridge Wells	Tunbridge Wells	Road	Surface preservation	Whole length	Condition survey
Dundale Road		Lamberhurst	Tunbridge Wells	Road	Surface preservation	From bridge near curling rink to gate approx. 750m from A21	Condition survey

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
East Cliff Road		Tunbridge Wells	Tunbridge Wells	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Eridge Road	A26	Tunbridge Wells	Tunbridge Wells	Road	Road renewal	From Eridge Road roundabout to pedestrian crossing (Summervale Road)	Condition survey
Etherington Hill		Speldhurst	Tunbridge Wells	Road	Surface preservation	From Barden Road to gateway near "Little Botte"	Condition survey
Forest Road		Royal Tunbridge Wells	Tunbridge Wells	Road	Surface preservation	From Camden Road to The Spread Eagle public house	Condition survey
Forest Road		Paddock Wood	Tunbridge Wells	Road	Surface preservation	From junction with Benhall Mill Road to Bayham Road (end of surface dressing)	Condition survey
Forest Road		Paddock Wood	Tunbridge Wells	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Goudhurst Road	A262	Goudhurst, Cranbrook, Biddenden	Tunbridge Wells	Road	Surface preservation	Corridor Scheme From Bluecoat Lane, Goudhurst to Biddenden High Street	Condition survey
Grosvenor Road	A26	Tunbridge Wells	Tunbridge Wells	Road	Road renewal	From junction with Hanover Road to A26 St Johns Road	Condition survey
Horns Road		Hawkhurst	Tunbridge Wells	Road	Surface preservation	From Delmonden Lane to Avardis Close	Condition survey
Iden Green Road		Benenden	Tunbridge Wells	Road	Surface preservation	From Standen Street to Benenden Crossroads	Condition survey
Langton Road		Tunbridge Wells	Tunbridge Wells	Drainage	Full survey to be undertaken and scheme developed	Outside No. 19	Customer enquiries
London Road	A26	Tunbridge Wells	Tunbridge Wells	Road	Road renewal	Extents to be determined	Condition survey

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Lucks Lane		Paddock Wood	Tunbridge Wells	Road	Surface preservation	From Maidstone Road to Queen Street (except level crossing)	Condition survey
Maidstone Road		Paddock Wood	Tunbridge Wells	Road	Surface preservation	From Badsell Road to Station Road	Condition survey
Maidstone Road		Paddock Wood	Tunbridge Wells	Road	Surface preservation	Church Road to A228 Pembury Northern Bypass (In front of hospice/near school)	Condition survey
Maidstone Road		Paddock Wood	Tunbridge Wells	Road	Surface preservation	From Mascalls Court Road to 'Kings Barn' (end of microsurfacing)	Condition survey
Major Yorks Road		Tunbridge Wells	Tunbridge Wells	Drainage	Full survey to be undertaken and scheme developed	Whole road	Section 19 Flooding Identification
Megrims Hill		Sandhurst	Tunbridge Wells	Road	Surface preservation	From Megrims Cottage to Sandhurst village gateway	Condition survey
Merriments Lane		Hawkhurst	Tunbridge Wells	Structures	Preventative maintenance to corrugated steel culvert	Canals Culvert (KCC Structure No. 94) carrying Kent Ditch under road	Condition survey
Mill Street and Sponden Lane		Benenden / Sandhurst	Tunbridge Wells	Road	Surface preservation	From end of high friction surfacing/junction with Standen Street ('Weald House') to Sponden Lane ('Sponden Oast')	Condition survey
Mount Ephraim	A264	Tunbridge Wells	Tunbridge Wells	Road	Road renewal	From Travelodge to Church Road	Condition survey
Mount Pleasant Road		Tunbridge Wells	Tunbridge Wells	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
North Hill Road		Hawkhurst	Tunbridge Wells	Road	Surface preservation	From Delmonden Lane to A268	Condition survey
North Road		Goudhurst	Tunbridge Wells	Road	Surface preservation	From Chequers Road to Ballards Hill	Condition survey
Parkwood Close		Tunbridge Wells	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Pembury Northern Bypass	A228	Pembury	Tunbridge Wells	Road	Surface preservation	From Maidstone Road to Pembury Road	Condition survey
Pembury Road	A264	Tunbridge Wells	Tunbridge Wells	Road	Surface preservation	From the junction with the A21 access roundabout (Tesco end) to the junction with Calverley Road	Condition survey
Petteridge Lane		Matfield and Brenchley	Tunbridge Wells	Road	Surface preservation	From Brenchley Road to Cryals Road	Condition survey
Powder Mill Lane		Southborough	Tunbridge Wells	Road	Surface preservation	From A26 to Yew Tree Road	Condition survey
Rusthall Road		Rusthall	Tunbridge Wells	Road	Surface preservation	From Coach Road to A264 (Dingley Dell)	Condition survey
Rye Road	A268	Cranbrook	Tunbridge Wells	Road	Road renewal	Extension - Garden Cottage to Marsh Quarter Lane	Condition survey
Rye Road	A268	Cranbrook	Tunbridge Wells	Road	Road renewal	Extents to be determined	Local needs
Rye Road		Cranbrook	Tunbridge Wells	Road	Surface preservation	From 'Little Fowlers' (near Water Lane) to 'Risden', (near Conghurst Lane)	Condition survey
Rye Road	A268	Cranbrook	Tunbridge Wells	Road	Road renewal	From Lomas Lane to property 'Rosemullion'	Condition survey

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Sandhurst Close		Tunbridge Wells	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sandhurst Park		Tunbridge Wells	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Sandhurst Road		Tunbridge Wells	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Showfields Road		Tunbridge Wells	Tunbridge Wells	Footway	Footway preservation	Entire length	Identified by survey
Sponden Lane		Sandhurst	Tunbridge Wells	Road	Surface preservation	From Sponden Lane triangle to A268 Megrims Hill	Condition survey
Staplehurst Road		Cranbrook	Tunbridge Wells	Road	Surface preservation	From Headcorn Road/Green Lane to Park Wood Lane	Condition survey
Stepneyford Lane		Cranbrook	Tunbridge Wells	Road	Road renewal	Extents to be determined	Condition survey
Stepneyford Lane		Cranbrook	Tunbridge Wells	Road	Road reconstruction (recycling)	From Little Maplesden to Colebrook Farm	Condition survey
Stonewall Park Road		Rusthall	Tunbridge Wells	Road	Surface preservation	From Langholm Road to cul-de-sac end	Condition survey
Tudeley Road		Tudeley, Tonbridge	Tunbridge Wells	Road	Surface preservation	From Somerhill School to Woodgate roundabout	Condition survey
Upper Grosvenor Road		Tunbridge Wells	Tunbridge Wells	Soft Landscape	Tree planting scheme	Various locations	Tree improvement scheme
Valley Road		Rusthall	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Water Lane		Hawkhurst	Tunbridge Wells	Road	Surface preservation	From Attwaters Lane to A268 Rye Road	Condition survey

TUNBRIDGE WELLS

Road Name	Road No.	Town/Village	District	Asset	Description of Works	Extents	Identification
Whetsted Road	A228	Paddock Wood	Tunbridge Wells	Road	Surface preservation	From Hop Farm roundabout to Five Oak Green roundabout	Condition survey
Wickham Gardens		Rusthall	Tunbridge Wells	Footway	Works type to be defined at design stage	Extents to be defined during design stage	Identified by survey
Woodsgate Corner	A228		Tunbridge Wells	Traffic Signals	Signal junction renewal	Junction with A264	Annual review of equipment age, specification and fault rate
Yew Tree Road/ Highfield Road		Southborough	Tunbridge Wells	Road	Surface preservation	From A26 to North Farm Road	Condition survey